

## **QUOTATION**

523830-H
A-2-01 CoPlace 1
2270 Jalan Usahawan 2
63000 Cyberjaya, Selangor
Malaysia
Phone (603) 8322 6393 Fax (603) 8322 6693

To: Date: 11/8/2022

**Quotation No:** G7/GLX/110822/1

Prepared by: Mohd Sani

GALAXY AEROSPACE (m) SDN BHD
Suite 11-14, Helicopter Center,
Malaysia International Aerospace Center
Sultan Abdul Aziz Shah Airport,
47200 SUBANG Selangor

Item: V/UHF AIRBONE TRANSCEIVER

Part Number: 6111325752

Serial Number: TBA

REPORT:

Initial Defect: Lithium Battery out of spec

Tear down inspection carried out and found:

Initial functional test carried out found:

• Visual and physical check to be carried out on item.

Item was externally cleaned and disassembled so that component per component troubleshooting and fault isolation detection was carried out and the following were found:

- Item to be disassembled and visual inspection to be carried out.
- Inspect and check on Lithium Battery.
- Lithium Battery on Protection Processor Module replaced.
- Loose article checks to be carried out.
- Soldering connection to be cleaned.

## Rectification Plan:

- a. Lithium Battery on Protection Procession Module to be replaced.
- b. Test the battery on board after replaced.
- c. Carry out loose article checks to ensure all parts are accounted for.
- d. Carry out continuity check to ensure no any shorting
- e. Clean all parts of dirt and rust.
- f. Reapply conformal coating.
- g. Reassemble all modules after checked, inspected and cleaned.
- h. Functional test the unit within a set duration of time to ensure stability of repair.
- i. Quality checks to ensure check and balance of items.

## **Service Cost:**

| No. | DESCRIPTION                               | AMOUNT (RM) |
|-----|---|-------------|
| 1   | Estimate Tear Down Inspection and Testing | 1,350.00    |
| 2   | Estimate Repair Services                  | 600.00      |
| 3   | Estimate Reassembly                       | 750.00      |
| 4   | Estimate Function Test                    | 150.00      |
| 5   | Estimate Final Tesy and Inspection        | 300.00      |
| 6   | Spare                                     | 350.00      |
|     | SUBTOTAL                                  | 3,500.00    |
|     | OTHER                                     |             |
|     | TOTAL                                     | 3,500.00    |

<sup>\*\*</sup> The current TDI only covers the manhours for TDI, as the repair manhours, pretesting and final testing hours dependent on the TDI findings.

Updated TDI shall be provided upon finalization of TDI process.

## Notes:

- 1) The quotation is valid for 30 days from quotation issuance.
- 2) Prices are based on effective price list at the date of quotation and maybe subject to variation.
- 3) Lead Time: 30 Days from receipt of quotation acceptance.
- 4) Payment Terms: 30 days after invoice issued.
- 5) G7 Aerospace Bank Details:

Bank Name : CIMB Bank Berhad

Bank Address : Prima 5-A, Jalan Teknokrat 5, 63000 Cyberjaya, Selangor, Malaysia

Account Name : G7 Aerospace Sdn Bhd
Account Number : 1255-0000424-05-9

Bank Swift Code : CIBBMYKL

Please contact us should you have any questions concerning this quotation, contact name, phone number.

For and on behalf, **G7 Aerospace Sdn Bhd** 

Sani

Mohd Sani bin Muhamad Yunos Operations Manager

THANK YOU FOR YOUR BUSINESS!