



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD

39, LOYANG WAY, SINGAPORE 508735

TEL : 65 65421121

FAX : 65 65425383

E-MAIL : michael\_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.

ATTN : Nur Syamim Syuhada Amdan

SUBJECT : Quotation

REF. : F21-014

PAGES : 1/1

DATE : 04/FEB/2022

Order No.	: PO-22-227		
Description	: Main Rotor Blade	Serial No.	: 25083
Part No.	: 355A11-0030-02	Job No.	: 15818
<b>Work Scope</b>			
S01B	Receiving / Inspection	US\$	481
B02 & 05	Replace Outboard & Inboard L/E strips	US\$	9,617
B06	Replace Lower Surface PU Tape	US\$	4,761
B10	Replace Trim Tabs (#4, #5 & #6)	US\$	1,886
S01A	Repaint & Static Balance	US\$	4,423
	<b>Total</b>	<b>US\$</b>	<b>21,168</b>
<b>Inspection Revealed</b>			
Inboard and Ourbord L/E Erosion Strips cracked. Lower Surface PU reverted Trim Tabs #4, #5 & #6 debonded Surface paint erosion			
<b>Terms &amp; Condition</b>			
Incoterms	: Ex-works		
TAT	: 6 weeks (ARO)		
Validity	: Till 31st March 2022		
Payment Terms	: Full payment prior to delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$481		
C of C will be issued after repair. End User : Royal Malaysian Navy (TDLM)			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay

Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
Name/Signature	Date