



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD

39, LOYANG WAY, SINGAPORE 508735

TEL : 65 65421121

FAX : 65 65425383

E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.

ATTN : Nur Syamim Syuhada Amdan

SUBJECT : Quotation

REF. : F21-070

PAGES : 1/2

DATE : 10/JUNE/2022

Purchase Order No.	: RMN-22-377		
Description	: Tail Rotor Blade	Serial No.	: 10792
Part No.	: 355A-12-0050-04	Job No.	: 15929
Work Scope			
S01B	Receiving / Inspection	US\$	481
B02A	Replace L/E Strip and Bond Strap (Non S/N Side)	US\$	4,275
B06	Replace Lower Surface PU (Both sides)	US\$	4,102
B71	Replace Laminated Bearings	US\$	3,889
S01	Repaint & Static Balance	US\$	6,175
		US\$	18,922
Inspection Revealed			
Leading Edge strip, Non S/N Side dented			
Lower Surface PU reverted			
Laminated Bearings cracked			
Surface paint erosion			
Terms & Condition			
Incoterms	: ex-works CTIPL		
TAT	: 4 weeks (ARO)		
Validity	: Till 30th July 2022		
Payment Terms	: Full payment prior top delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$481		
Military use - C of C will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval.

Thank you

Best Regards

Michael Tay

Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____ Name/Signature	_____ Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD
39, LOYANG WAY, SINGAPORE 508735
TEL : 65 65421121 FAX : 65 65425383
E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.
ATTN : Nur Syamim Syuhada Amdan
SUBJECT : Quotation

REF. : F21-070
PAGES : 2/2
DATE : 10/JUNE/2022

Purchase Order No.	: RMN-22-377		
Description	: Tail Rotor Blade	Serial No.	: 16469
Part No.	: 355A-12-0050-10	Job No.	: 15930
Work Scope			
S01B	Receiving / Inspection	US\$	481
B06	Replace Lower Surface PU (Both sides)	US\$	4,102
B71	Replace Laminated Bearings	US\$	3,889
S01	Repaint & Static Balance	US\$	6,175
		US\$	14,647
Inspection Revealed			
Lower Surface PU reverted Laminated Bearings cracked Surface paint erosion			
Terms & Condition			
Incoterms	: ex-works CTIPL		
TAT	: 4 weeks (ARO)		
Validity	: Till 30th July 2022		
Payment Terms	: Full payment prior top delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$481		
Military use - C of C will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval.

Thank you

Best Regards

Michael Tay

Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
Name/Signature	Date