



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD

39, LOYANG WAY, SINGAPORE 508735

TEL : 65 65421121

FAX : 65 65425383

E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.

ATTN : Nur Syamim Syuhada Amdan

SUBJECT : Quotation

REF. : F22-013

PAGES : 1/2

DATE : 14/Feb/2023

Purchase Order No.	: RMN-23-897		
Description	: Tail Rotor Blade	Serial No.	: 16240
Part No.	: 355A-12-0050-10	Job No.	: 16132
Work Scope			
Receiving / Inspection		US\$ 500	
Replace Lower Surface PU (Both sides)		US\$ 4,356	
Repaint & Static Balance		US\$ 6,775	
		US\$ 11,631	
Inspection Revealed			
Lower Surface PU reverted Surface paint eroded			
Terms & Condition			
Incoterms	: Ex-works CTIPL		
TAT	: 4 weeks (ARO)		
Validity	: Till 30th Mar 2023		
Payment Terms	: Full payment prior to delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$500		
Military End-User - C of C will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

Best Regards

Michael Tay

Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____ Name/Signature	_____ Date



COMPOSITE TECHNOLOGY INTERNATIONAL PTE LTD
39, LOYANG WAY, SINGAPORE 508735
TEL : 65 65421121 FAX : 65 65425383
E-MAIL : michael_tay@composite-technology.com.sg

TO : Galaxy Aerospace (M) Sdn Bhd.
ATTN : Nur Syamim Syuhada Amdan
SUBJECT : Quotation

REF. : F22-013
PAGES : 2/2
DATE : 14/Feb/2023

Order No.	: PO-22-6215		
Description	: Main Rotor Blade	Serial No.	: 259
Part No.	: C621A1006101	Job No.	: 16133
Work Scope			
Receiving / Inspection		US\$	625
Replace Trim Tabs #1 - 3		US\$	2,335
Repaint & Static Balance		US\$	6,000
	Total	US\$	8,960
Inspection Revealed			
Trim Tabs damaged Surface Paint eroded			
Terms & Condition			
Incoterms	: Ex-works		
TAT	: 4 weeks (ARO)		
Validity	: Till 30th Mar 2023		
Payment Terms	: Full payment prior to delivery		
Currency	: Quoted in United States Dollars		
Evaluation Charges if RAI	: US\$625		
CAAM Release will be issued after repair			
CTIPL Standard Terms and Conditions apply. Copy attached.			

Please advise cost approval. Thank you

**Please forward updated original log card for blade S/N 259 for verification and repair entries.
(Incorrect log card received. Log card received is for blade S/N 1045)**

Best Regards

Michael Tay
Dy. General Manager, Operations.

Cost Accepted	<input type="checkbox"/>
RAI (Return As Is)	<input type="checkbox"/>
_____ Name/Signature	_____ Date