



# PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE  
 JTC AVIATION 2 BUILDING #09-07  
 SELETAR AEROSPACE PARK  
 65-6817-3370

797523  
 SINGAPORE  
 www.precisionaviationgroup.com  
 GST: 201737172D

## REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

**No. 5604887** Pg:1/1

GALAXY AEROSPACE (M) SDN BHD  
 Attn: AQILAH BINTI MOHD HANAFI  
 SUITE 11-14, HELICOPTER CENTRE,  
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
 SULTAN ABDUL AZIZ SHAH AIRPORT  
 SUBANG 47200  
 MALAYSIA  
 Tel. : +60377347226

Our Ref : Q5604887  
 Terms : PREPAID WIRE TRANSFR  
 Our Contact : Ratan Pandey  
 eMail : rpandey@heliparts.com  
 Valid Until : Sep-15-2022  
 Incoterms : FCA - FREE CARRIER (ORIGIN)  
 Quote Date : Aug-16-2022

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	400-015525-5011 RT-5000 FLEXCOM TRANSCEIVER  CERTIFICATION: FAA 8130  THE ABOVE COST IS VALID FOR STANDARD REPAIR ONLY. THERE WILL BE A REVISED QUOTE IF THE UNIT REQUIRES REPAIR WORK MORE THAN QUOTED ABOVE.	RP	1 EA	45 Days	\$ 7,950.00 EA	\$ 7,950.00

					<b>Sub Total:</b>	\$ 7,950.00
					<b>Total:</b> [USD]	\$ 7,950.00

Ratan Pandey,  
 Copyright (c)PENTAGON2000 Software, Inc.  
 Ser #:[2000.21267] Ver 2019.01.01 Build 14

ORIGINAL