

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHAR KHAN SUITE 11-14, HELICOPTER CENTRE

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT SUBANG 47200

MALAYSIA

Tel.: +603-7455 0555

No. 5605965

Pg:1/1

Our Ref Your Ref

: SO# 5603827 : PO-23-6356 : PREPAID WIRE TRANSFR

Terms **Our Contact**

eMail

Valid Until

:Ratan Pandey :rpandey@heliparts.com :Apr-06-2023 :FCA - FREE CARRIER (ORIGIN) :Mar-07-2023 Incoterms

Quote Date

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	8210-310 PROP GOVERNOR ALT#:3057250-01 Serial No(s).:1992710 ECCN: 9A991.d Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND Unit received in bad condition Unit failed incoming bench tests Replacement for beta valve plunger assy requir Replacement for circuit nameplate required USI Speeder spring seat ID worn, Requires relacem Unit requires standard overhaul and replacement Standard overhaul USD 2,250.00 Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, NOTE- This unit is on hold pending your faxed/ any applicable taxes, freight or customs charge during the course of the repairs listed above. If a	ADVI ed US 0 115. ent, U nt of pa TEST emaile s. This add'l re	1 EA D 5,750.00 00 SD 1450.00 arts ED AND RECERTIFIED d authorization to proce estimate does not inclue epairs are needed, we we	45 Days	\$ 9,565.00 EA ate does not include ailures that may be found with a revised estimate.	\$ 9,565.00
				Sub Total:	\$ 9,565.00	
Ratan Pa	andey,				Total: [USD]	\$ 9,565.00