

KESUMA TECHNOLOGY SDN.BHD

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

Selangor Darul Ehsan, MALAYSIA. Tel: +603-7832 2998/7398 Fax: +603-7832 4998

: Kasim Hj Ismail

From

To : GALAXY AEROSPACE (M) SDN BHD

Suite 11-14, Helicopter Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia

Phone : +603 7734 7226 Date : 20/09/2024
Fax : +603 7734 7526 Currency : USD

Attn : Ashila Naja Mohd Zulkaple Reference : GALAXY/R/0015/2024

Re : QUOTATION FOR REPAIR

Please find our quotation with regards to your Purchase Order No: MMA-23-798

No.	Part No	Description	Serial No	Qty	Total Cost	Delivery (Status)
1	3G6410A00133	TAIL ROTOR BLADE ASSY	V4842	1	20,301.16	210 days after your PO
	Breakdown - Refer to the attached \	Norkshop Report				
	1) Detailed Inspection (Blade to be sent to Italy for repair due to dummy heater mat found debonded)					
	2) Repair activity to perform additional work or to replace other components					
			Total Cost	. –	20,301.16	

Estimated / Price of New : USD 60,155.82

Note:

Offer Validity
 30 days from the date of quotation
 Terms of Payment
 To be made in full before delivery

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

DN BHD

5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certificate of Conformance / EASA certificate
6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the

official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2

working days for confirmation of purchase

Warranty period shall be as follows:

1) New Condition : 12 months against manufacturer faults except for consumable items.

2) Repair Condition : 6 Months or 500 hrs against manufacturer faults.