



406 Dividend Drive
 Peachtree City, Georgia 30269
 Phone (770) 632-1851
 Fax: (770) 632-1852

Repair Estimate

| | | |
|-----------------------------|------------------------------|--|
| LOG CARD: | YES <input type="checkbox"/> | NO <input checked="" type="checkbox"/> |
| SPECIAL INSTRUCTION: | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| UNIT MISUSED: | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| PICTURES: | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

| | |
|----------------------------|-------------------|
| DATE: | 15-Jun-2020 |
| PRIME REFERENCE: | 45960 |
| CUSTOMER REFERENCE: | GAM-PO-20-331 (2) |
| PART NUMBER: | 174250-92 |
| SERIAL NUMBER: | 24042 |
| DESCRIPTION: | OXYGEN MASK |
| WORK REQUESTED: | OVERHAUL |

EVALUATIONS / FINDINGS:
 TESTED AND INSPECTED. FOUND HARNESS ASSEMBLY LEAKING. MASK ASSEMBLY IS DAMAGED (FACE SEAL)

CORRECTIVE ACTIONS TO BE CARRIED OUT:
 UNIT REQUIRES OVERHUAL, REPLACEMENT OF HARNESS, REPLACEMENT OF FACE SEAL.

PARTS REPLACED OR REPAIRED

EXCLUSIONS: **CONDITION AFTER COMPLETION:**

| PART NUMBER | DESCRIPTION | STATUS | QUANTITY | PRICE |
|-------------|--------------|----------|----------|------------|
| 270530-00 | HARNESS ASSY | REPLACED | 1 | \$2,500.00 |
| 270363-00 | FACE SEAL | REPLACED | 1 | \$1,200.00 |

FLAT RATE:

TOTAL QUOTE

TOTAL QUOTE OPTION #1

TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)

EVALUATION FEE IF QUOTE DENIED

COMMENTS: PRIME WILL ABSORB THE CHARGES FOR THE FACE SEAL.

Approval Signature: _____

Name: _____ Date: _____