



COMPONENT REPAIR REPORT

1. Customer: Galaxy Aerospace	4. Cust PO#: MMA-22-362	7. TSN /CSN: - / -
2. WO #: 784	5. Qty:1	8. TSO /CSO : 0 / -
3. PN #: 524-031	6. SN: 764	9. TSR /CSR : - / -

A. Removal Reason

Overhaul

B. Receiving Findings

1. Unit received normal in carton box.
2. Unit internal and external surface are clean and in good condition.
3. Amendment status A, B, C, D, E, F, G, H are previously complied.

C. Shop Findings

1. Disassembled complete unit for details overhaul inspection.
2. Armature (PN 505455-1) commutator surface is clean.
3. Other hardware found in good conditions.
4. The unit would be overhauled in this shop visit.
5. No SB & AD required to comply in this shop visit.

D. This component repair report is prepared by (Name & Date): Samhari Abdul Majid / 26 Sep 2022



Attachment 1: Material Report

PART NUMBER	DESCRIPTION	QTY	REASON
505455-1	Armature assembly	1	Rework - balance
LJQ1QG040025AL	Screw	1	Overhaul. Replaced new.
22296AG030008L	Screw	4	Overhaul. Replaced new.
R9QV030AL	Flat washer	4	Overhaul. Replaced new.
R9QV040AL	Washer	4	Overhaul. Replaced new.
V025051H	Nut	4	Overhaul. Replaced new.
408764B	Brush	4	Overhaul. Replaced new.
DZQ1QG040008UL	Screw	4	Overhaul. Replaced new.
S4	Spring washer	4	Overhaul. Replaced new.
22541N060	Check nut	1	Overhaul. Replaced new.
46208A	Flat washer	1	Overhaul. Replaced new.
409487	Spring	1	Overhaul. Replaced new.
409049	Washer	1	Overhaul. Replaced new.
P720184	Nut	1	Overhaul. Replaced new.
V052170D	Lock washer	1	Overhaul. Replaced new.
409190	Screw	4	Overhaul. Replaced new.
46100	Tab washer	4	Overhaul. Replaced new.
410997	Bearing	1	Overhaul. Replaced new.
B8Q1ZH040010APA	Screw	4	Overhaul. Replaced new.
P711933-1	Lining	1	Overhaul. Replaced new.
410964	Bearing	1	Overhaul. Replaced new.
B8Q1QV030010AL	Screw	4	Overhaul. Replaced new.
V922005K	Retaining ring	1	Overhaul. Replaced new.
P723856	Screw	8	Overhaul. Replaced new.
409258	Gasket	1	Overhaul. Replaced new.
409182	Insulator	1	Overhaul. Replaced new.
401219	Tab washer	2	Overhaul. Replaced new.
VXQ1QV050012AL	Screw	2	Overhaul. Replaced new.
VTQV050L	Spring washer	2	Overhaul. Replaced new.
P722699	Nut	2	Overhaul. Replaced new.
90006604	Spring washer	3	Overhaul. Replaced new.
P722698	Nut	3	Overhaul. Replaced new.
J101236C	O-ring	1	Overhaul. Replaced new.