



METAL BAYU SDN. BHD.

(201801010749)

C-20-11, Empire Damansara SOHO 1,

PJU 8/8, Damansara Perdana, 47820 Petaling Jaya, Selangor, Malaysia.

Tel: +6019-3899312 Email: info@metalbayu.com.my

WE NAVIGATE SUCCESS

Galaxy Aerospace (M) Sdn. Bhd.

A-01-02, Blok A,
Bangunan Perdagangan Siera,
Ara Damansara, Jalan PJU 1A/5A,
47301 Petaling Jaya, Selangor.

QUOTATION	
No. :	GAM/MBSB/0039/1408/24
Date :	14/08/2024
Page :	1
Created by :	Batrisya

Attn : En. Sumaili Sulaiman

RE: REFURBISHMENT OF AIRCRAFT TYPE KING AIR-9M-PTD

NO.	DESCRIPTION	QTY	PRICE	AMOUNT
1.	Three-Layer Exterior Polishing + Wax	1.00	15,000.00	15,000.00
2.	Pilot & Co-Pilot Seat Leather Replacement- Inclusive of Armrest, back panel and Headrest inclusive Leg Structure Painting	2.00	16,000.00	32,000.00
3.	Three-Observer Seats come with Sheep Skin Leather Replacement Inclusive of Armrest, back panel and Headrest inclusive Leg Structure Painting	3.00	15,000.00	45,000.00
4.	Attendant Seat – Leather & Cushion Refurbish	3.00	3,500.00	7,000.00
5.	Lavatory Seat – Leather & Cushion Refurbish	1.00	5,000.00	5,000.00
6.	Additional Scope of Work		8,000.00	8,000.00
	a) Side Wall Cleaning, Repair and Paint Touch-up			
	b) Ceiling Panel Cleaning and Paint Touch-up			
	c) Emergency Exit Door Leather Trim Replacement			
	d) Curtain Cleaning			
	e) Staircase Side Panel – Cleaning and Paint Touch-up			
	f) Staircase string leather wrap (10cm x 15cm) with Velcro strap			
	g) Partition Wood Veneer – Cleaning and Minor Repair			

Note: All the leathers and foams come with burn certificate from OEM

Subtotal (MYR)	112,000.00
Total (MYR)	112,000.00

Terms and Conditions

- Prices quoted are in **MYR** and are valid for thirty (30) days unless noted otherwise.
- This business dealing is governed under the Malaysian Law.

Approved by:



HAZLIN BIN MAHAYUDIN
GENERAL MANAGER