



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

No. 5609042 Pg:1/1

GALAXY AEROSPACE (M) SDN BHD
 Attn: NUR AFRINA AZHAR KHAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +603-7455 0555

Our Ref : SO# 5605459
Your Ref : PO-24-8189
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : Sep-27-2024
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : Aug-28-2024

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	1363A020001 FWD COMPRESSOR ASSY Serial No(s): 1363-02422 ECCN: 9A991.d Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND ADVISE Preliminary Inspection: WIRE HARNESS FOUND GOOD COIL HAS HIGH AMPS AND LOW VOLTAGE, REQUIRES REPLACEMENT. PULLEY FOUND WITH WORN BEARING, REQUIRES REPLACEMENT. UNIT FOUND WITH LOW PRESSURE DUE TO WORN PISTON RINGS, REQUIRES REPLACEMENT. UNIT REQUIRES STANDARD OVERHAUL - USD 9,450.00 Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, TESTED AND RECERTIFIED. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____	OH	1 EA	60 Days	\$ 9,450.00 EA	\$ 9,450.00

Sub Total:	\$ 9,450.00
Total: [USD]	\$ 9,450.00

 RIDZUAN BIN YA'AKOB,