

# Quotation

	GALAXY AEROSPACE (M) SDN BhD Subang Selangor	Date:	19/9/2021
Attn	En Azizul / Ms Dian	No.	Msv 004/GA2022

#### Quotation To supply and install Polycabonate Roof at MIMOS Walkway Area.

No	Description	Qty	Price/unit	Amount
1	To replace cable burnt and make a good connection fron	1 Lot	RM250.00	RM250.00
	indoor to compressor unit			
2	To do major servicing and chemical clean, check motor condenser, and compressor	1 Lot	RM280.00	RM280.00
3.	To refill R410 refrigerent gas	1 Lot	RM120.00	RM120.00
4	To supply and replace capacitor 35uf for ompressor unit	1 Lot	RM80.00	RM80.00

Grand Total: RM730.00

Please do not hesitate to call us if you have any inquiries, we hope the price quote will be considered and approve by the Management.

### Term of payment

Two (2) weeks upon job completion and submission of invoice

Thank you

MAHIR SEGALA VENTURES MOHAMAD FADZLI BIN AHMAD MAHIR PROJECT MANAGER 013 - 2559407

## Service Report

Date : 19/9/2022

S/R No : MSV004/GAS2022

Re : Faulty air conditioning wall mounted split unit asset No 016 located at Worksyop Galaxy Aerospace Subang Selangor.

Received complaint from Ms Qistana on 15/9/2022, the air conditioning unit not running and trip at all once switch on.

## Action taken.

To do thorough checking and found the existing power cable from cooling coil to compressor unit was burnt and shorting at the connection area. Condenser fin dirty, gas not enough.

Temporary action have been taken to avoid power trip. We have made new power connection at the compressor unit and cutt off the burnt cable. Test run the unit and found unit running but not cold enough.

We strongly advise to do major servicing and chemical clean the condenser unit, refill R410 gas and replace the old capacitor to ensure the compressor unit running well and under specifications.

Prepared by Mohamad Fadzli bin Ahmad Mahir Operation Manager Mahir Segala Ventures