

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHAR KHAN SUITE 11-14, HELICOPTER CENTRE,

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Tel.: +603-7455 0555

No. 5607608

Pg:1/1

Our Ref : SO# 5604493 Your Ref

: PO-23-7206 : PREPAID WIRE TRANSFR Terms

Our Contact : Ratan Pandey eMail

: rpandey@heliparts.com : Jan-03-2024 Valid Until

: FCA - FREE CARRIER (ORIGIN) : Dec-04-2023 Incoterms

Quote Date

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	3G6320V03853 MGB Cooling Fan Serial No(s).: 00474R ECCN: 9A991 Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND A Preliminary Inspection: Unit received with mechanical damage Unit failed incoming test Casing found damaged due to customer induced of Bearings worn, requires replacement Sheath worn, requires replacement Splined shaft worn, requires replacement Unit requires replacement of parts and standard or Standard overhaul USD 8,450.00 Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, TE NOTE- This unit is on hold pending your faxed/em any applicable taxes, freight or customs charges. during the course of the repairs listed above. If add	damage verhaul siled au This est d'I repai	1 EA AND RECERTIFIED. Athorization to proceed. Timate does not include a rs are needed, we will contain the contained to th	60 Days SD 3,995.00 This estimate do ny add'l failures	that may be found	\$ 12,445.00
RIDZUAN BIN YA'AKOB, Total: [USD]						\$ 12,445.00 \$ 12,445.00