

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

797523 SINGAPORE www.precisionaviationgroup.com GST: 201737172D

REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: MUZDALIFAH

SUITE 11-14, HELICOPTER CENTRE,

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Tel.: +60377347226

No. 5607526

Pg:1/1

Our Ref : SO# 5604468 Your Ref

: PO-23-7223 : PREPAID WIRE TRANSFR Terms

Our Contact : Ratan Pandey

: rpandey@heliparts.com : Dec-20-2023 eMail

Valid Until

: FCA - FREE CARRIER (ORIGIN) Incoterms

: Nov-20-2023 **Quote Date**

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	YAW TRIM ACTUATOR Serial No(s).: 7244 ECCN: 9A991.d Reported By Customer: Unit is INOP. Inspect and Advise Preliminary Inspection: Unit received in fair condition Unit failed incoming due to defective electronic cor Bearing and clutch require cleaning Unit requires replacement of parts and standard rep Standard repair USD 11,500.00 Corrective Action: Unit is to be Repaired per CMM and tested and rec NOTE- This unit is on hold pending your faxed/ema any applicable taxes, freight or customs charges. T during the course of the repairs listed above. If add Approval Signature:	ertified ailed a his es 'I repa	1 EA d board, requires replaced d.	Γhis estimate do	es not include that may be found a revised estimate.	\$ 12,950.00
					Sub Total:	\$ 12,950.00
					Total: [USD]	\$ 12,950.00
RIDZUAN BIN YA'AKOB,					I Ulai. [UOU]	φ 1∠, 9 50.00