

## PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

## REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: MUZDALIFAH

SUITE 11-14, HELICOPTER CENTRE,

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

**SUBANG 47200 MALAYSIA** 

Tel.: +60377347226

No. 5607531

Pg:1/1

Our Ref : SO# 5604576 Your Ref

: PO-23-7333 : PREPAID WIRE TRANSFR Terms

**Our Contact** : Ratan Pandey eMail

: rpandey@heliparts.com : Dec-20-2023 Valid Until

: FCA - FREE CARRIER (ORIGIN) Incoterms

: Nov-20-2023 **Quote Date** 

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	8210-310 PROP GOVERNOR ALT#: 3057250-01 Serial No(s).: 16627055 ECCN: 9A991.d  Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND AD  Preliminary Inspection: Unit received in fair exterior condition Unit failed incoming test Magnetic coil assy found damaged, requires replace Unit requires replacement of parts and standard ov Standard overhaul USD 2,295.00  Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, TEST  NOTE- This unit is on hold pending your faxed/emaany applicable taxes, freight or customs charges. T during the course of the repairs listed above. If add  Approval Signature:	ement erhaul STED / ailed au his est	AND RECERTIFIED.  Journal of the state of th	inv add'l failures	that may be found	\$ 6,440.00
				Sub Total:	\$ 6,440.00	
RIDZUAN BIN YA'AKOB,					Total: [USD]	\$ 6,440.00
`ib4	(a) DENTACON 2000 Software Inc					