



## **SOLID PARTNERS SDN BHD (502421-U)**

31-2, Jalan Kasturi 3, Plaza Kasturi, Off Jalan Balakong,  
43200 Cheras, Selangor Darul Ehsan, Malaysia.

Tel : +603 9075 6101 Fax : +603 9075 6102 Email : enquiries@solidpartners.com.my

### **GOODRICH RESCUE HOIST 44316 SERIES FIX FIRM PRICE (FFP) REPAIR GUIDELINE FOR 2020**

**VALIDITY: 01<sup>ST</sup> JANUARY 2020 UNTIL 31<sup>ST</sup> DECEMBER 2020**

- 
- 1. TEARDOWN, TEST AND EVALUATION – RESCUE HOIST\* RM 49,900.00**  
Unit received, tested, inspected and certified to approve technical documentation with no other work performed. In the event any of the following occur, customer decide not to have the item repair or overhaul, no fault is found (customer reason for return was not confirmed); or unit is deemed beyond economical repair – TT&E charges still apply. (TT&E fees are waived upon customer's approval of recommended repair and quotation)
- 2. CLUTCH REPLACEMENT – RESCUE HOIST\* RM 53,793.00**  
Clutch only replacement will include as needed: Overload Clutch (External Hoist Only); functional check and acceptance testing of the equipment. Equipment will be issued a Certificate of Conformance and FAA8130 Dual Release form as applicable.
- 3. MINOR REPAIR + CLUTCH – RESCUE HOIST\* RM 153,806.00**  
Minor repair of the rescue hoist would include as needed: external/cosmetic repairs to include paint, damaged fairings; seals, gears within gearbox, ball bearings; cable replacement; Overload Clutch (External Hoist Only); functional check and acceptance testing of the equipment. Equipment will be issued a Certificate of Conformance and FAA8130 Dual Release form as applicable.
- 4. MAJOR REPAIR – RESCUE HOIST\* RM 315,007.00**  
Major repair of the rescue hoist as needed replacement of internal components requiring complete and/or partial disassembly to the level wind or drum assembly. Repair or replacement as required components such as level-wind assembly, ball spline, drum replacement, repair of housing, harness, fan assembly replacement, motor component repair and/or replacement (EMI Filter, stator housing, circuit board assemblies, Overload Clutch (External Hoist Only), motor rebuild, harness assembly, function check and acceptance testing of the equipment. Equipment will be issued a Certificate of Conformance and FAA8130 Dual Release form as applicable.
- 5. OVERHAUL – RESCUE HOIST\* RM 587,819.00**  
Overhaul of the rescue hoist consist of complete disassembly of the equipment, cleaning and inspection (Non-Destructive Testing, Dimensional and Visual) of the internal components; replacement of selected service life components such as level wind assembly, level wind shoe and screw, bearings, seals, gaskets, packing preformed, brake retainer packing, compression springs, brake pistons, cable assembly, spring, carrier retainer, friction discs, Overload Clutch (External Hoist Only), gears and pinions; motor repair or modification as needed and component covered under major repair scope. Equipment will be issued a Certificate of Conformance and FAA8130 Dual Release form as applicable.

*\*Fix Firm Price covers application of mandatory service bulletins, yet does not cover equipment received with missing components. Customer will be notified at completion of incoming inspection of missing components and will be quoted at replacement spares price.*

