

## QUOTATION

To:

**GALAXY AEROSPACE (M) SDN BHD**

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,

Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426

Faks: +603-7887 0526

Attn: En Nor Azman Huzir / En Faiz Fahmi Johari

From : Kasim Hj Ismail

Pages : 01

Date : 24-Mar-2021

Currency : **USD**

AC Type/SN : **AW139**

Reference : GALAXY0542/03/2021

**RE: SPARES / EXCHANGE QUOTATION**

Below is the quotation for your RFQ: Email on 19/03/21, SB139-444 Part III, IV and XIII

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
<b>PART II</b>							
<b>3G7810R00911 REAR LH EXHAUST FLANGE REPAIR</b>							
1	3G7810A18731	CENTRAL FLANGE LH ASSY	EA	1	1,612.87	1,612.87	TBA
2	NAS 1200-3-5	RIVET, SOLID	EA	16	0.35	5.60	280
3	MS20615-4M4R	RIVET,SOLID	EA	17	0.35	47.25	90
				(MOQ:135)			
4	MS20615-4M5	RIVET,SOLID	KG	0.1	265.74	26.57	90
5	3G7810A09752	SPECIAL RUBBER	EA	3	67.28	201.84	90
6	3G7810A12651	SPECIAL BUSHING	EA	3	138.96	416.88	90
7	3G7810A14031	CENTRAL CUP ASSY	EA	1	1,575.47	1,575.47	310
8	3G7810A14131	INTERNAL CUP ASSY EXHAUST LH	EA	1	1,073.18	1,073.18	290
9	3G7810A14331	EXTERNAL CUP ASSY EXHAUST LH	EA	1	1,073.18	1,073.18	260
10	MS16625-1087	RING,RETAINING,INTERNAL	EA	3	4.46	13.38	90
11	AW008TZ-02-132	WASHER,FLAT	EA	3	27.68	83.04	90
	(request P/N 999-0066-02-132)						
<b>PART IV</b>							
<b>3G7810R00912 REAR RH EXHAUST FLANGE REPAIR</b>							
1	3G7810A18831	CENTRAL FLANGE RH ASSY	EA	1	1,612.87	1,612.87	TBA
2	MS20615-3M4	RIVET,SOLID	KG	0.1	265.74	26.57	90
3	A297A04TW02	RIVET,BLIND,TITANIUM	EA	22	16.27	406.75	90
				(MOQ:25)			
4	3G7810A09752	SPECIAL RUBBER	EA	3	67.28	201.84	90
5	3G7810A12651	SPECIAL BUSHING	EA	3	138.96	416.88	90
6	3G7810A14031	CENTRAL CUP ASSY	EA	1	1,575.47	1,575.47	310
7	3G7810A14231	INTERNAL CUP ASSY EXHAUST RH	EA	1	1,073.18	1,073.18	240
8	3G7810A14431	EXTERNAL CUP ASSY EXHAUST RH	EA	1	1,073.18	1,073.18	260
9	MS16625-1087	RING,RETAINING,INTERNAL	EA	3	4.46	13.38	90
10	AW008TZ-02-132	WASHER,FLAT	EA	3	27.68	83.04	90
	(request P/N 999-0066-02-132)						
<b>PART XIII</b>							
<b>3G7810R00612 REAR RH EXHAUST REPAIR</b>							
1	3G7810A17951	REAR EXHAUST REINFORCEMENT	EA	1	325.26	325.26	TBA
2	3G7810A18351	REAR EXHAUST REINFORCEMENT	EA	2	212.04	424.08	TBA
3	A297A04TW01	RIVET,BLIND,TITANIUM	EA	10	9.67	96.70	90
4	A297A04TW02	RIVET,BLIND,TITANIUM	EA	20	16.27	325.40	90
5	MS20615-3M3	RIVET,SOLID	KG	0.1	265.74	26.57	90

Below is the quotation for your RFQ: Email on 19/03/21, SB139-444 Part III, IV and XIII

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
6	MS20615-3M3R	RIVEST,SOLID		65	0.31	20.15	310
7	MS20615-4M4R	RIVET,SOLID		20 (MOQ: 135)	0.35	47.25	90

**Grand Total : 13,877.84**

Note:

- 1) Offer validity : 30 days from the date of quotation
- 2) Terms of payment : To be made in full before delivery.
- 3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation
- 4) Delivery : Subject to prior sale
- 5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
- 6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

Warranty period shall be as follows:

- 1) New condition : 12 months against manufacturer faults except for consumable items.
- 2) Repair condition : 6 months or 500 hrs against manufacturer faults

  
for KESUMA TECHNOLOGY SDN BHD  
