

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152-X) D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

QUOTATION

10:		
GALAXY AEROSPACE (M) SDN BHD	From	: Kasim Hj Ismail
79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,		
Ara Damansara, 47301 Petaling Jaya, Selangor	Pages	: 01
Tel: +603-7887 0426	Date	: 18-Jan-2022
Faks: +603-7887 0526	Currency	: USD
Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple	AC Type/SN	: AW139
	Reference	: GALAXY020/01/2022
RE- SPARE OLIOTATION		

SPARE QUOTATION

G6320A16651			Qty	Unit Price	Total Price	Delivery Status
J0320A10031	CAP WASHER, CLAMPING ADAPTER	EA	1	861.94	861.94	90
W001BS01A030	SHIM, TAIL ROTOR DRIVE FLANGE	EA	1	71.36	71.36	90
W001BS01A035	SHIM, TAIL ROTOR DRIVE FLANGE	EA	2	71.36	142.72	90
W001BS01A040	SHIM, TAIL ROTOR DRIVE FLANGE	EA	2	71.36	142.72	90
W001BS01A045	SHIM, TAIL ROTOR DRIVE FLANGE	EA	2	71.36	142.72	90
W001BS01A050	SHIM, TAIL ROTOR DRIVE FLANGE	EA	1	71.36	71.36	90
W001BS01A055	SHIM, TAIL ROTOR DRIVE FLANGE	EA	1	71.36	71.36	90
W001BS01A060	SHIM, TAIL ROTOR DRIVE FLANGE	EA	2	71.36	142.72	90
W001BS01A070	SHIM, TAIL ROTOR DRIVE FLANGE	EA	2	71.36	142.72	90
W001BS01A100	SHIM, TAIL ROTOR DRIVE FLANGE	EA	1	77.39	77.39	90
W011TB05-B-10	BOLT, HEX HEAD	EA	6	42.24	253.44	90
IS27253-2	PLATE, IDENTIFICATION	EA	MOQ:5	11.30	56.50	90
	V001BS01A035 V001BS01A040 V001BS01A045 V001BS01A055 V001BS01A055 V001BS01A060 V001BS01A070 V001BS01A100 V011TB05-B-10	V001BS01A035SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A040SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A045SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A050SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A055SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A060SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A070SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A100SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A100SHIM, TAIL ROTOR DRIVE FLANGEV001BS01A100SHIM, TAIL ROTOR DRIVE FLANGEV011TB05-B-10BOLT, HEX HEAD	V001BS01A035SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A040SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A045SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A050SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A055SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A055SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A060SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A070SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A100SHIM,TAIL ROTOR DRIVE FLANGEEAV001BS01A100SHIM,TAIL ROTOR DRIVE FLANGEEAV011TB05-B-10BOLT,HEX HEADEA	V001BS01A035SHIM, TAIL ROTOR DRIVE FLANGEEA2V001BS01A040SHIM, TAIL ROTOR DRIVE FLANGEEA2V001BS01A045SHIM, TAIL ROTOR DRIVE FLANGEEA2V001BS01A050SHIM, TAIL ROTOR DRIVE FLANGEEA1V001BS01A055SHIM, TAIL ROTOR DRIVE FLANGEEA1V001BS01A060SHIM, TAIL ROTOR DRIVE FLANGEEA2V001BS01A060SHIM, TAIL ROTOR DRIVE FLANGEEA2V001BS01A070SHIM, TAIL ROTOR DRIVE FLANGEEA2V001BS01A100SHIM, TAIL ROTOR DRIVE FLANGEEA1V011B05-B-10BOLT, HEX HEADEA6	V001BS01A035SHIM,TAIL ROTOR DRIVE FLANGEEA271.36V001BS01A040SHIM,TAIL ROTOR DRIVE FLANGEEA271.36V001BS01A045SHIM,TAIL ROTOR DRIVE FLANGEEA271.36V001BS01A050SHIM,TAIL ROTOR DRIVE FLANGEEA171.36V001BS01A055SHIM,TAIL ROTOR DRIVE FLANGEEA171.36V001BS01A055SHIM,TAIL ROTOR DRIVE FLANGEEA171.36V001BS01A060SHIM,TAIL ROTOR DRIVE FLANGEEA271.36V001BS01A070SHIM,TAIL ROTOR DRIVE FLANGEEA271.36V001BS01A100SHIM,TAIL ROTOR DRIVE FLANGEEA177.39V011TB05-B-10BOLT,HEX HEADEA642.24	V001BS01A035 SHIM, TAIL ROTOR DRIVE FLANGE EA 2 71.36 142.72 V001BS01A040 SHIM, TAIL ROTOR DRIVE FLANGE EA 2 71.36 142.72 V001BS01A040 SHIM, TAIL ROTOR DRIVE FLANGE EA 2 71.36 142.72 V001BS01A045 SHIM, TAIL ROTOR DRIVE FLANGE EA 2 71.36 142.72 V001BS01A050 SHIM, TAIL ROTOR DRIVE FLANGE EA 1 71.36 142.72 V001BS01A050 SHIM, TAIL ROTOR DRIVE FLANGE EA 1 71.36 71.36 V001BS01A055 SHIM, TAIL ROTOR DRIVE FLANGE EA 1 71.36 71.36 V001BS01A060 SHIM, TAIL ROTOR DRIVE FLANGE EA 2 71.36 142.72 V001BS01A070 SHIM, TAIL ROTOR DRIVE FLANGE EA 2 71.36 142.72 V001BS01A100 SHIM, TAIL ROTOR DRIVE FLANGE EA 1 77.39 77.39 V011B05-B-10 BOLT, HEX HEAD EA 6 42.24 253.44

Note:

- 1) Offer validity
- 2) Terms of payment
- 3) Cancellation
- 4) Delivery
- 5) Condition
- 6) Confirmation

: 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

: To be made in full before delivery.

: There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

: Subject to prior sale

: NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate

: Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

Warranty period shall be as follows:

- 1) New condition
- 2) Repair condition
- : 12 months against manufacturer faults except for consumable items.
- : 6 months or 500 hrs against manufacturer faults

