

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152-X)

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

Selangor Darul Ehsan, MALAYSÍA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

: Kasim Hj Ismail

QUOTATION

To

GALAXY AEROSPACE (M) SDN BHD

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,

Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426 Faks: +603-7887 0526

Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

Pages : 01

From

Date : 3-Feb-2022 Currency : **USD** AC Type/SN : **AW139**

Reference : GALAXY039/02/2022

RE: SPARE QUOTATION

Below is the quotation for your RFQ: Email on 03/02/2022

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	3G6210A01152 (request P/N 3G6210A01151)	POCKET COVER	EA	1	522.89	522.89	30
2	3G1010G00131 (request P/N 3G1005G00232)	ENGINE AIR INTAKE COVER,LH	EA	3	376.26	1,128.78	90
3	3G1005G00232) 3G1010G00231 (request P/N 3G1005G00332)	ENGINE AIR INTAKE COVER, RH	EA	3	368.60	1,105.80	90
4	3G1005G00332) 3G1005G04131 (request P/N 3G1005G00431)	ENGINE EXHAUST AIR DUCT COVER LH/RH	EA	3	250.04	750.12	90

Grand Total : 3,507.59

Note:

1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

2) Terms of payment : To be made in full before delivery.

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the
official Purchase Order (PO) and customer's must respond to Kesuma Technology within

2 working days for confirmation of purchase.

Warranty period shall be as follows:

1) New condition : 12 months against manufacturer faults except for consumable items.

2) Repair condition : 6 months or 500 hrs against manufacturer faults

for KESUMA TECHNOLOGY SDN BHD