

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152.x) D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

QUOTATION

| То: | | |
|---|------------|---------------------|
| GALAXY AEROSPACE (M) SDN BHD | From | : Kasim Hj Ismail |
| 79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre, | | |
| Ara Damansara, 47301 Petaling Jaya, Selangor | Pages | : 01 |
| Tel: +603-7887 0426 | Date | : 27-Jul-2022 |
| Faks: +603-7887 0526 | Currency | : USD |
| Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple | AC Type/SN | : AW139 |
| | Reference | : GALAXY251/07/2022 |
| | | |

RE: SPARE QUOTATION

| Below is the quotation for your RFQ: Email on 26/07/2022 | | | | | | | |
|--|--------------|-----------------|-----|-----|---------------|-------------|-----------------|
| No | Part Number | Description | U.M | Qty | Unit Price | Total Price | Delivery Status |
| 1 | 3G3240V00332 | MAIN BRAKE ASSY | EA | 2 | 27,115.55 | 54,231.10 | 90 |
| | | | | | Grand Total : | 54,231.10 | |

Note:

| 1) Offer validity | : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes |
|---------------------|--|
| 2) Terms of payment | : To be made in full before delivery. |
| 3) Cancellation | : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation |
| 4) Delivery | : Subject to prior sale |
| 5) Condition | : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate |
| 6) Confirmation | : Confirmation of availability of goods will be given within 5 working days upon receipt of the |
| | official Purchase Order (PO) and customer's must respond to Kesuma Technology within |
| | 2 working days for confirmation of purchase. |

Warranty period shall be as follows:

- 1) New condition
- : 12 months against manufacturer faults except for consumable items.
- 2) Repair condition
- : 6 months or 500 hrs against manufacturer faults

