



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD
 Attn: AQILAH BINTI MOHD HANAFI
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +60377347226

No. 5605195	Pg:1/1
--------------------	--------

Our Ref : SO# 5603419
 Your Ref : PO-22-5753
 Terms : PREPAID WIRE TRANSFR
 Our Contact : Ratan Pandey
 eMail : rpandey@heliparts.com
 Valid Until : Nov-04-2022
 Incoterms : FCA - FREE CARRIER (ORIGIN)
 Quote Date : Oct-05-2022

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	400-015525-5011 FLEXCOMM II TRANSCIEVER Serial No(s): 78180 Reported By Customer: UNIT REQUIRES REPAIR, INSPECT AND ADVISE Preliminary Inspection: Unit received in fair condition Unit failed incoming test PA hi-split failure due to obsolescence issues with PA, motherboard and DSP, requires replacement USD 27,495.00 Multiple CSBs' required to update synth/receiver module MTM module needs alignment of audio Unit requires standard repair and replacement of parts Standard repair USD 7,950.00 Corrective Action: UNIT WILL BE REPAIRED AS PER CMM, TESTED AND RECERTIFIED. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____	RP	1 EA	28 Days	\$ 35,445.00 EA	\$ 35,445.00

					Sub Total:	\$ 35,445.00
					Total:	[USD] \$ 35,445.00