

QUOTATION

To:

GALAXY AEROSPACE (M) SDN BHD
79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,
Ara Damansara, 47301 Petaling Jaya, Selangor
Tel: +603-7887 0426
Faks: +603-7887 0526
Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

From : Kasim Hj Ismail
Pages : 01
Date : 11-Jan-2023
Currency : USD
AC Type/SN : AW139
Reference : GALAXY007/01/2023

RE: SPARE QUOTATION

Below is the quotation for your RFQ: Email on 06/01/2023

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	109-0040-51-103	SERVOCYLINDER ASSY,HYDR	N	1	15,484.94	15,484.94	90
2	109-0900-39-107	MAIN ACTUATOR	N	1	18,084.00	18,084.00	90
		(REPAIRED UNIT)					
2a	109-0900-39-107	MAIN ACTUATOR	N	1	(4,941.00)	(4,941.00)	
		(CORE UNIT)					
3	109-0130-60-109	ROCKER ARM ASSY	N	1	1,136.40	1,136.40	90
4	109-0133-04-109	TAIL ROTOR STICK ASSY	N	2	1,335.26	2,670.52	90
5	109-0110-21-103	STATIONARY SCISSOR SLEEVE	N	2	401.69	803.38	90
6	109-0110-54-111	LEVER ASSY,PLANE CONTROL	N	1	2,581.98	2,581.98	90
7	109-0110-69-105	SLEEVE,ROTATING SWASHPLATE	N	1	632.68	632.68	90
8	109-0134-10-105	HALF-SCISSORS ASSY,LOWER	N	1	3,710.51	3,710.51	90

Grand Total : 40,163.41

Note:

- 1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes
- 2) Terms of payment : To be made in full before delivery.
- 3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation
- 4) Delivery : Subject to prior sale
- 5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
- 6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

Warranty period shall be as follows:

- 1) New condition : 12 months against manufacturer faults except for consumable items.
- 2) Repair condition : 6 months or 500 hrs against manufacturer faults


for KESUMA TECHNOLOGY SDN BHD