



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD
 Attn: NUR AFRINA AZHAR KHAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +603-7455 0555

No. 5605952	Pg:1/1
--------------------	--------

Our Ref : SO# 5603828
 Your Ref : PO-23-6356
 Terms : PREPAID WIRE TRANSFR
 Our Contact : Ratan Pandey
 eMail : rpandey@heliparts.com
 Valid Until : Apr-02-2023
 Incoterms : EXW - EX WORKS
 Quote Date : Mar-03-2023

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	8210-310 PROP GOVERNOR ALT#: 3057250-01 Serial No(s): 15679597 ECCN: 9A991.d Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND ADVISE Preliminary Inspection: Unit received in bad condition Unit failed incoming bench tests Reset step cover required USD 1,425.00 Reset post and airbleed lever assy required USD 3,250.00 Replacement for beta valve plunger assy required USD 5,750.00 Replacement for shim Qty 1 ea required USD 175.00 Replacement for circuit nameplate required USD 115.00 Unit requires standard overhaul and replacement of parts Standard overhaul USD 2,250.00 Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, TESTED AND RECERTIFIED. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate.	OH	1 EA	35 Days	\$ 12,965.00 EA	\$ 12,965.00
Approval Signature: _____				Date: _____		

					Sub Total:	\$ 12,965.00
					Total:	[USD] \$ 12,965.00