



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD
 Attn: NUR AFRINA AZHAR KHAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +603-7455 0555

No. 5606806	Pg:1/1
--------------------	--------

Our Ref : SO# 5604185
Your Ref : PO#23-6830
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : Aug-23-2023
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : Jul-24-2023

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	1152546-2 STARTER GENERATOR ALT#: 300SGL146Q-2 Serial No(s): 1152546-02997 ECCN: 9A991.d Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND ADVISE Preliminary Inspection: Unit received in bad condition Unit failed incoming tests T-block cover missing, requires replacement USD 595.00 Armature balance ring loose, requires rework USD 1,250.00 Speed sensor found bent, requires replacement USD 750.00 Thermal switch assy found broken, requires replacement USD 1,195.00 Unit requires replacement of parts and standard overhaul Standard overhaul USD 3,250.00 Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, TESTED AND RECERTIFIED. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____	OH	1 EA	60 Days	\$ 7,040.00 EA	\$ 7,040.00

					Sub Total:	\$ 7,040.00
					Total: [USD]	\$ 7,040.00

 RIDZUAN BIN YA'AKOB,