



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD
 Attn: MUZDALIFAH
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +60377347226

No. 5607347	Pg:1/1
--------------------	--------

Our Ref : SO# 5604426
 Your Ref : PO-23-7173
 Terms : PREPAID WIRE TRANSFR
 Our Contact : Ratan Pandey
 eMail : rpandey@heliparts.com
 Valid Until : Nov-17-2023
 Incoterms : FCA - FREE CARRIER (ORIGIN)
 Quote Date : Oct-18-2023

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	8930-112B90H101 SMOKE DETECTOR Serial No(s): 14662 ECCN: EAR99 Reported By Customer: Unable to push to test. Inspect and Advise Preliminary Inspection: Unit received in fair exterior condition Unit failed incoming test PCB / Light array assy failed, requires replacement USD 5,645.00 Unit requires cleaning and calibration Unit requires replacement of parts and standard repair Standard repair USD 3,450.00 Corrective Action: Unit is to be Repaired per CMM and tested and recertified. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____	RP	1 EA	60 Days	\$ 9,095.00 EA	\$ 9,095.00

					Sub Total:	\$ 9,095.00
					Total:	[USD] \$ 9,095.00