

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152-X)

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

Selangor Darul Ehsan, MALAYSIA.

Tel: +603-7832 2998/7398 Fax: +603-7832 4998

(SST NO: B16-2207-32100006)

: Kasim Hj Ismail

: 17-Nov-2023

QUOTATION

To

GALAXY AEROSPACE (M) SDN BHD

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,

Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426 Faks: +603-7887 0526

Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

Currency : USD
AC Type/SN : AW139

Reference : GALAXY303/11/2023

: 01

RE: SPARE QUOTATION

Below is the quotation for your RFQ: Email on 16/11/2023

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	504784	SUMP GASKET	N	2	191.14	382.28	90
2	3G6230A03851	PEELING SHIM INNER	N	3	889.64	2,668.92	90
3	3G6420A02051	PEELING SHIM	N	8	149.49	1,195.92	90
4	3G6420A02151	PEELING SHIM FLAP STOP	N	8	93.38	747.04	90
5	1134275-17	RIGHT SIDE RECEIVER DRYER	N	1	1,099.04	1,099.04	90
		ASSEMBLY					
6	1134275-18	LEFT SIDE RECEIVER DRYVER	N	1	1,988.94	1,988.94	90
		ASSEMBLY					

Grand Total : 8,082.14

From

Pages

Date

Note:

1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

2) Terms of payment : To be made in full before delivery.

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate

: Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within

2 working days for confirmation of purchase.

Warranty period shall be as follows:

6) Confirmation

1) New condition : 12 months against manufacturer faults except for consumable items.

2) Repair condition : 6 months or 500 hrs against manufacturer faults

for KESUMA DECHNOLOGY SDN BHD