



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

No. 5607757 Pg:1/1

GALAXY AEROSPACE (M) SDN BHD
 Attn: NUR AFRINA AZHAR KHAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +603-7455 0555

Our Ref : SO# 5604727
Your Ref : PO-23-7506
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : Feb-09-2024
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : Jan-10-2024

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	822-1828-061 DISPLAY CONTROL PANEL Serial No(s): 3HL3V ECCN: 7A994 Reported By Customer: Unit is INOP. Inspect and Advise Preliminary Inspection: Unit received in fair condition Unit failed incoming tests Menu/Data rotary switch fails intermittently, requires replacement USD 1,075.00 Baro rotary switch has worn out detent, requires replacement USD 785.00 All outer knobs require repaint Unit requires standard repair USD 3,950.00 Corrective Action: Unit is to be Repaired per CMM and tested and recertified. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____	RP	1 EA	45 Days	\$ 5,810.00 EA	\$ 5,810.00

Sub Total:	\$ 5,810.00
Total: [USD]	\$ 5,810.00

 RIDZUAN BIN YA'AKOB,