



# PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE  
 JTC AVIATION 2 BUILDING #09-07  
 SELETAR AEROSPACE PARK  
 65-6817-3370

797523  
 SINGAPORE  
 www.precisionaviationgroup.com  
 GST: 201737172D

## REPAIR / OVERHAUL QUOTE

**For : Account No. [GALAXYMY]**

GALAXY AEROSPACE (M) SDN BHD  
 Attn: NUR AFRINA AZHAR KHAN  
 SUITE 11-14, HELICOPTER CENTRE,  
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
 SULTAN ABDUL AZIZ SHAH AIRPORT  
 SUBANG 47200  
 MALAYSIA  
 Tel. : +603-7455 0555

**No. 5607852** Pg:1/1

**Our Ref** : SO# 5604729  
**Your Ref** : PO-23-7501  
**Terms** : PREPAID WIRE TRANSFR  
**Our Contact** : Ratan Pandey  
**eMail** : rpandey@heliparts.com  
**Valid Until** : Feb-25-2024  
**Incoterms** : FCA - FREE CARRIER (ORIGIN)  
**Quote Date** : Jan-26-2024

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	<b>109-0718-46-103</b> VENTILATION FAN <b>ALT#:</b> 70-279 <b>Serial No(s):</b> 10525 <b>Schedule B:</b> 8803.30.0030 <b>ECCN:</b> 9A991.d  Reported By Customer: Unit is INOP. Inspect and Advise  Preliminary Inspection: Unit received in fair condition Unit failed incoming tests Control PCB found inoperative, requires replacement Filter PCB found inoperative, requires replacement USD 1,035.00 Motor bearings are worn. requires replacement Unit requires replacement of parts and standard repair Standard Repair USD 2,850.00  Corrective Action: Unit is to be Repaired per CMM and tested and recertified.  NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate.  Approval Signature: _____ Date: _____	RP	1 EA	35 Days	\$ 3,885.00 EA	\$ 3,885.00

<b>Sub Total:</b>	\$ 3,885.00
<b>Total:</b> [USD]	\$ 3,885.00

\_\_\_\_\_  
 RIDZUAN BIN YA'AKOB,