

**KESUMA TECHNOLOGY SDN.BHD**

(Co No: 762152-X)

D-7-02, Capital 4, Oasis Square,
No. 2, Jalan PJU 1A/7A, Ara Damansara,
47301 Petaling Jaya,
Selangor Darul Ehsan, MALAYSIA.
Tel : +603-7832 2998/7398
Fax : +603-7832 4998

(SST NO: B16-2207-32100006)

QUOTATION

To:

GALAXY AEROSPACE (M) SDN BHD79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,
Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426

Faks: +603-7887 0526

Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

From : Kasim Hj Ismail

Pages : 01

Date : 6-Mar-2024

Currency : **USD**AC Type/SN : **AW139**

Reference : GALAXY065/03/2024

RE: SPARE QUOTATION

Below is the quotation for your RFQ: Email dated 27/02/2024

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	J00765-178-61D6 (request P/N J00765178FLS5)	O-RING	N	2	186.31	372.62	90
2	3G6320V03854 (request P/N 3G6320V03853)	FAN MGB COOLING	N	1	25,665.62	25,665.62	90
3	2-011N1173-70	O-RING	N	8	4.03	32.24	90
4	1134275-18	LEFT SIDE RECEIVER DRYVER ASSEMBLY	N	1	2,346.96	2,346.96	90
5	1134275-17	RIGHT SIDE RECEIVER DRYER ASSEMBLY	N	1	1,099.04	1,099.04	90

Grand Total : 29,516.48

Note:

- 1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes
- 2) Terms of payment : To be made in full before delivery.
- 3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation
- 4) Delivery : Subject to prior sale
- 5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
- 6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

Warranty period shall be as follows:

- 1) New condition : 12 months against manufacturer faults except for consumable items.
- 2) Repair condition : 6 months or 500 hrs against manufacturer faults

for KESUMA TECHNOLOGY SDN BHD

