

**KESUMA TECHNOLOGY SDN.BHD** 

Co No: 762152:X D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

(SST NO: B16-2207-32100006)

## QUOTATION

т	0	•	
	υ	٠	

10.		
GALAXY AEROSPACE (M) SDN BHD	From	: Kasim Hj Ismail
79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,		
Ara Damansara, 47301 Petaling Jaya, Selangor	Pages	: 01
Tel: +603-7887 0426	Date	: 15-Mar-2024
Faks: +603-7887 0526	Currency	: USD
Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple	AC Type/SN	: AW139
	Reference	: GALAXY079/03/2024

## Delaw is the sustation for your DEC. Enail detail 12/02/2024

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	3G6410A03551	PEELING SHIM	N	10	29.11	291.10	90
2	NOR494-1E5-12	PIN, COTTER	N	10	12.52	125.20	90
3	3P7117A35251	BUSHING	N	2	269.97	539.94	90
4	3G6430A00335	HALF SCISSOR ASSY	N	2	3,500.22	7,000.44	90
	(request P/N						
	3G6430A00355)						
5	3G6430A00355	HALF SCISSOR ASSY	N	2	3,500.22	7,000.44	90
6	3G6430A02353	SCISSOR COUPLING	Ν	4	1,668.28	6,673.12	90
					Grand Total :	21.630.24	

Note:

1) Offer validity

2) Terms of payment

3) Cancellation

- 4) Delivery
- 5) Condition
- 6) Confirmation

: Subject to prior sale

: There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

: NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate

: 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

: Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within

2 working days for confirmation of purchase.

: To be made in full before delivery.

Warranty period shall be as follows:

- 1) New condition
- 2) Repair condition

: 12 months against manufacturer faults except for consumable items. : 6 months or 500 hrs against manufacturer faults

CHNOLOGY for KESI DN BHD