



REPAIR INVOICE

MY AERO SPARES PLT (reg LLP0027219-LGN)

No 5, Jalan Seroja 5, Taman Seroja,
BBST, Sepang 43900, Selangor, Malaysia.
sales@myaerospares.com | +60 17 6889 773

INVOICE: 20220057 YOUR RO: PO-24-7678 DATE: 16 FEBRUARY 2024

BILL TO	SHIP TO	INSTRUCTIONS
GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. ATTN: MUZDALIFAH HANANI Tel: +60377347226	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	PART NUMBER	DESCRIPTION	PRICE
01	7037620-814	DISPLAY UNIT SN:08035715 Trouble Found: *Initial inspection found that 3rd party warranty seals were intact, no external discrepancies noted. *Data plate indicates that Mods A-C, E, G, and J are incorporated. *Functional test found that the display is INOP, but fan is operational. *Removed case for internal inspection and troubleshooting. *Further testing revealed that the CPU CCA is the cause of the display being INOP. *Installed a test CPU CCA and found that the display is operational, but front unit requires alignment. *Unit requires disassembly, cleaning, replacement of CPU CCA, reassembly, inspection, alignment as required, run Extended Thermal and Environmental testing and final testing in accordance with manufacturer specifications.	

