



# REPAIR INVOICE

**MY AERO SPARES PLT** (reg LLP0027219-LGN)

No 5, Jalan Seroja 5, Taman Seroja,  
BBST, Sepang 43900, Selangor, Malaysia.  
sales@myaerospares.com | +60 17 6889 773

**INVOICE: 20220064      YOUR RO: PO-24-7733      DATE: 08 MARCH 2024**

BILL TO	SHIP TO	INSTRUCTIONS
<b>GALAXY AEROSPACE (M) SDN BHD</b> Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	<b>GALAXY AEROSPACE (M) SDN BHD</b> Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.  ATTN: Muzdalifah Hanani Roslizan Tel: +603-7455 0555	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	QTY	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
01	01	3G6230A00732	ROTATING SCISSOR ASSY SN: 1632  REPLACE WORN BUSHING  TAT: 12 DAYS	USD 6,500.00	USD 6,500.00

<b>SUBTOTAL</b>	USD 6,500.00
<hr/>	
<hr/>	
<b>TOTAL</b>	USD 6,500.00

Thank you for your business!