



REPAIR INVOICE

MY AERO SPARES PLT (reg LLP0027219-LGN)

No 5, Jalan Seroja 5, Taman Seroja,
BBST, Sepang 43900, Selangor, Malaysia.
sales@myaerospares.com | +60 17 6889 773

INVOICE: 20220082

YOUR RO: RMN-24-1462

DATE: 30 APRIL 2024

BILL TO	SHIP TO	INSTRUCTIONS
GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. ATTN: Muzdalifah Hanani Roslizan Tel: +603-7455 0555	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
01	CP1976FB01	SWITCH SELECTOR, ICS BOX SN: 6296 SHOP FINDING: AUDIO OUTPUT DISTORTION DUE TO GROUNDING CAME LOOSE. UNIT RECEIVED LOW LEVEL. HIGH IMPEDENCE (BN-HZ) ACTION REQUIRED: UNIT DISASSEMBLED AND CLEANED. GROUNDING RE-SECURED. ALL PUSH BUTTON SWITCHES WILL BE LUBRICATED AND CLEANED. UNIT REPAIRED AND TESTED IN ACCORDANCE WITH CURRENT MANUFACTURE SPECIFICATIONS. TAT: 45 Days DUAL RELEASE EASA/FAA 6 Months warranty	USD 3,200.00	USD 3,200.00

SUBTOTAL USD 3,200.00

TOTAL USD 3,200.00

Thank you for your business!