



REPAIR INVOICE

MY AERO SPARES PLT (reg LLP0027219-LGN)

No 5, Jalan Seroja 5, Taman Seroja,
BBST, Sepang 43900, Selangor, Malaysia.
sales@myaerospares.com | +60 17 5089 773

INVOICE: 20220057 YOUR RO: PO-24-7678 DATE: 16 MAY 2024

BILL TO	SHIP TO	INSTRUCTIONS
GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. ATTN: MUZDALIFAH HANANI Tel: +60377347226	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	PART NUMBER	DESCRIPTION	PRICE
01	7037620-814	DISPLAY UNIT SN:08035715 Trouble Found: *Initial inspection found that 3rd party warranty seals were intact, no external discrepancies noted. *Data plate indicates that Mods A-C, E, G, and J are incorporated. *Functional test found that the display is INOP, but fan is operational. *Removed case for internal inspection and troubleshooting. *Further testing revealed that the CPU CCA is the cause of the display being INOP. *Installed a test CPU CCA and found that the display is operational, but front unit requires alignment. *Unit requires disassembly, cleaning, replacement of CPU CCA, reassembly, inspection, alignment as required, run Extended Thermal and Environmental testing and final testing in accordance with manufacturer specifications.	

ITEM	PART NUMBER	DESCRIPTION	PRICE
		<p>Replacement Parts Required:</p> <p>PN: 7026421-905 DESC: CPU CCA QTY: 1</p> <ul style="list-style-type: none"> • To release with EASA/FAA Dual Release • 12 Months warranty for replacement parts and labor • Unit will be ready to ship within 4 days after quote approved and payment received. <p>Labor</p> <p>Parts</p>	<p>USD 7,000.00</p> <p>USD 68,480.00</p>

SUBTOTAL USD 75,480.00

TOTAL USD 75,480.00

Thank you for your business!