



# REPAIR INVOICE

**MY AERO SPARES PLT** (reg LLP0027219-LGN)

No 5, Jalan Seroja 5, Taman Seroja,  
BBST, Sepang 43900, Selangor, Malaysia.  
sales@myaerospares.com | +60 17 6889 773

INVOICE: 20220064      YOUR RO: PO-24-7733      DATE: 07 OCT 2024

BILL TO	SHIP TO	INSTRUCTIONS
<b>GALAXY AEROSPACE (M) SDN BHD</b> Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	<b>GALAXY AEROSPACE (M) SDN BHD</b> Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.  ATTN: Muzdalifah Hanani Roslizan Tel: +603-7455 0555	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	QTY	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
01	01	3G6230A00732	ROTATING SCISSOR ASSY SN: 1632  REPLACE WORN BUSHING  SHOP FINDING:  DURING INSPECTION FOR WORN BUSHING BENYOND LIMIT, SHOP FOUND GROOVED PIN AND NEED TO BE REPLACED.	USD 6,500.00	USD 6,500.00
			REPLACEMENT PARTS: 3G6230A01852AA / PIN  TAT: 12 DAYS	USD 1,500.00	USD 1,500.00

ITEM	QTY	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
					

SUBTOTAL USD 8,000.00

---

TOTAL USD 8,000.00

---

Thank you for your business!