



HELIFT ENGINEERING (M) SDN BHD (1366067-T)
 No 23, Jalan Permata 2/KS9, Taman Perindustrian Air Hitam, 41200 Klang, Selangor.
 Tel:+60331227791 Email: enquiry@helift.com.my

Invoice No: INV-2108/0462
 DO No : DO-2108/0462
 Date : 25/08/2021
 PO No : AZQT2108/0136

Invoice

Billing Address :

GALAXY AEROSPACE (M) SDN BHD
 11-14 HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE,
 SULTAN ABDUL AZIZ SHAH AIRPORT,
 47200 SUBANG, SELANGOR
 TEL : FAX :

Delivery Address

11-14 HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE,
 SULTAN ABDUL AZIZ SHAH AIRPORT,
 47200 SUBANG, SELANGOR
 TEL : FAX :

Attn : Mr Mohammad Nizam Jaafar **Currency :** RINGGIT MALAYSIA **Terms :** C.O.D.

| No | Description | Quantity | Unit Price | Discount | Amount |
|----|--|----------|------------|----------|----------|
| 1 | TO CHECKING AND RECTIFY WIRING CONTROL CABLE CRANE 6 TON | 1 JOB | 350.00 | | 350.00 |
| 2 | TO RENTAL MOBILE SKYLIFT (1 DAY) | 1 UNIT | 1,400.00 | | 1,400.00 |

Note:
Job Done
SVR No:HL 10854, 12/08/2021
Description:Breakdown (UNIKL MIAT HANGAR 2)

RINGGIT MALAYSIA : ONE THOUSAND SEVEN HUNDRED AND FIFTY ONLY

Grand Total : RM 1,750.00

E. & O.E

Any discrepancies regarding this invoice should be lodged within SEVEN (7) days

Payment by cheque should be crossed and made payable to

HELIFT ENGINEERING (M) SDN BHD
 Alliance Bank Malaysia Berhad 011850010067031





HELIFT ENGINEERING (M) SDN BHD (1366067-T)
 No 23, Jalan Permata 2/KS9, Taman Perindustrian Air
 Hitam, 41200 Klang, Selangor.
 Tel:+60331227791 Email: enquiry@helift.com.my

DO No : DO-2108/0462
 Date : 25/08/2021
 PO No :
 Terms : C.O.D.

Delivery Order

Billing Address :

GALAXY AEROSPACE (M) SDN BHD
 11-14 HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE,
 SULTAN ABDUL AZIZ SHAH AIRPORT,
 47200 SUBANG, SELANGOR

TEL :

FAX :

Delivery Address :

11-14 HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE,
 SULTAN ABDUL AZIZ SHAH AIRPORT,
 47200 SUBANG, SELANGOR

TEL :

FAX :

| No | Description | Quantity |
|----|--|----------|
| 1 | TO CHECKING AND RECTIFY WIRING CONTROL CABLE CRANE 6 TON | 1 JOB |
| 2 | TO RENTAL MOBILE SKYLIFT (1 DAY) | 1 UNIT |

Note:

Job Done

SVR No:HL 10854, 12/08/2021

Description:Breakdown (UNIKL MIAT HANGAR 2)

Complaints if any should be lodged within (7) days after delivery of goods. We will not be held responsible for any defects if brought to our notice thereafter.

Total : 2

E. & O.E

Received Above goods In Good Order And Condition,

Goods received by

.....
 Name, Signature, Date & company Stamp



.....
 For HELIFT ENGINEERING (M) SDN BHD



HELIFT ENGINEERING (M) SDN BHD 202001009747 (1366067-T)

No.23, Jalan Permata 2/KS9, Taman Perindustrian Air Hitam
41200 Klang, Selangor Darul Ehsan
TEL: +6019 7128039 EMAIL: tsk.helift@gmail.com

SERVICE/REPAIR REPORT

- Chain Hoist
- Wire Rope Hoist
- Goods Hoist
- Monorail Crane
- EOT Crane
- Gantry Crane
- Jib Crane
- Semi Portal

DATE : 12/8/2021
SR NO : HL 10854

Customer: Unkl Sabang Works Order No:

Address: Demoj. JKR 2814 Capacity: 6 ton Control Design: Pendent Serial No: 96531409

Hoist Model: Creep Motor: PMA No:

| NO | ITEM | 1 | 2 | 3 | NO | ITEM | 1 | 2 | 3 | NO | LUBRICATION |
|----|-----------------------------|---|---|---|----|-------------------------------|---|---|---|----|---|
| 1 | Hoist Suspension | | | | 21 | Long travelling Contactors | | | | 1 | Check oil level, main gear |
| 2 | Rope/Chain | | | | 22 | Isolator Switch | | | | 2 | Check oil level, creep speed gear |
| 3 | Bottom Block | | | | 23 | Travel Wheels | | | | 3 | Grease pinion drive |
| 4 | Top Block, Traverse | | | | 24 | Pinion Drive | | | | 4 | Grease drive gear |
| 5 | Drum/Chain Collector | | | | 25 | Cross Travel Drive Motor | | | | 5 | Grease rope/Grease chain |
| 6 | Rope Guide/Chain Guide | | | | 26 | Brake, Drive Motor | | | | 6 | Grease limit switch operation rod |
| 7 | Pressure Ring | | | | 27 | Coupling | | | | 7 | Check oil of both crane motor |
| 8 | Drum Housing | | | | 28 | Crane Runway & Suspension | | | | | Oil Changes:..... |
| 9 | Gear; Main Speed | | | | 29 | Crane Girder, Crane weld | | | | | Any Oil leaks:..... |
| 10 | Gear; Creep Speed | | | | 30 | Crane & Carriage | | | | | |
| 11 | Motor; Main Speed | | | | 31 | Main Bolts; Fixing Bolts | | | | | |
| 12 | Motor; Creep Speed | | | | 32 | Cabin; Control Units | | | | | |
| 13 | Safety Limit Switch | | | | 33 | Crane Wheels | | | | | Report: |
| 14 | Main Brake/Safety Clutch | | | | 34 | Gear; Crane Travel Drive | | | | | Col. 1: Item is in order |
| 15 | Creep Speed Brake | | | | 35 | Motor; Crane Travel Drive | | | | | Col. 2: Item requires attention |
| 16 | Insulation | | | | 36 | Brake; Crane Travelling Motor | | | | | Col. 3: Item requires immediate repair or replacement |
| 17 | Current Collectors | | | | 37 | Wiring | | | | | |
| 18 | Control Switches | | | | 38 | Fuses | | | | | Remarks: |
| 19 | Main Lift Contactors | | | | | | | | | | |
| 20 | Cross Travelling Contactors | | | | | | | | | | |

Job Carried Out: attend breakdown. we check one found pendent cable lose exact connect. And install use connect back cable. Testing ok.

| ITEM WE USED | | | ITEM WE RECOMMEND TO REPLACE | | |
|--------------|-------------|----------|------------------------------|------------------|----------|
| QTY. | DESCRIPTION | PART NO. | QTY. | DESCRIPTION | PART NO. |
| | | | 1 | Remote @ control | 1 Set. |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Working Hours (Site): From 10.00 am To 11.00 am

Working Hours (W/S): (Hours)

Travelling Hours: 1 hour

Travelling Distance:

Service Completed by: Shasi @ Eshen

Transportation Registration No: 8214 8773

Respective customer was informed about the found defects and danger resulting therefrom

Service/Repair Completed & Checked

Name: **MOHD SHAH BIN ABU BAKAR**
 Charge Man
 Dept: Maintenance, Mgmt & Services
 Unkl Malaysian Institute Of Aviation Technology

 (Signature Of Service Technician)

 (Signature & Stamp Of Customer)