

TEARDOWN REPORT

3410 WEST MATHIS STREET Lincoln, NE 68524

402.475.2611 - 800.562.6377

Fax: 402.479.4213 CRS#: JGVR194F

Attention

MUZDALIFAH HANANI

Customer

Galaxy Aerospace (M) Sdn Bhd *

Customer P.O. MMA-24-953 Prepay - Wire

Payment Terms

Fax#

Part#

066-03137-3200 **Unit Description ELECTRONIC DISPLAY**

Serial# 4322 Model ED-551A **Email**

muzdalifah@galaxyaerospace.my

Work Order KEUMA

Work Order Description ELECTRONIC DISPLAY

Date

May 01, 2024 Registration# M70-01

Reported Discrepancy

Discrepancy: Display intermittent. Evaluate for repair.

Inspection Findings

Preliminary Findings: Could not duplicate discrepancy. Bench checked unit and found that the LVPS filter capacitors are showing signs of wear, the front lens filter is in poor condition, and the HVPS is suspected to be intermittently defective.

Tech Notes

| ***THIS IS | A PREL | IMINARY | ESTIMATE | ONLY*** |
|------------|--------|----------------|-----------------|---------|
|------------|--------|----------------|-----------------|---------|

Please advise. Thank you!

| | Check here if you | wish to have your | rejected parts | returned to you. | Additional freigh | t may be incurred. |
|--|-------------------|-------------------|----------------|------------------|-------------------|--------------------|
|--|-------------------|-------------------|----------------|------------------|-------------------|--------------------|

Check here if you require OEM parts and do not wish to have PMA parts installed on this unit.

Flat Rate Repair Salvage Part - Yes or No: YES

Estimated Labor \$1,443.00 **Estimated Parts** \$5,407.00 Misc Charges \$255.47

Estimated Total \$7,105.47

NOTE: The lens filter would be a salvage part and is in good

condition.

Part Lead Time: 1 week

| ٩F | P | 'R | O | VAI | L Al | JTI | НΟ | RIZ | ZAT | ΓIC | N | SI | GN | IA٦ | ΓU | RE | : |
|----|---|----|---|-----|------|-----|----|-----|-----|-----|---|----|----|-----|----|----|---|
| | | | | | | | | | | | | | | | | | |

Date:

DECLINE SIGNATURE:

Date:

Your account terms are Pre-Pay (Wire or Credit Card). Your completed unit will ship after payment is received. Miscellaneous charges may include freight, loaner freight, sales taxes, recertification charges, hazardous waste, or any other charges outside normal parts and labor, and are subject to change. By signing this form, you consent that Duncan Aviation may use a fabricated part during the repair/overhaul of this unit.

Note: All vendor exchange transactions may be subject to additional billing pending evaluation by the vendor.

Please respond within 5 days to avoid being billed rental fees on the Duncan loaner

Please sign one of the options above and return this fax (402.479.4213) or email to