

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152:X) D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

(SST NO: B16-2207-32100006)

QUOTATION

Т	n	•	
	v		

GALAXY AEROSPACE (M) SDN BHD	From	: Kasim Hj Ismail
79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,		
Ara Damansara, 47301 Petaling Jaya, Selangor	Pages	: 01
Tel: +603-7887 0426	Date	: 27-Sep-2023
Faks: +603-7887 0526	Currency	: USD
Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple	AC Type/SN	: AW139
	Reference	: GALAXY262/09/2023
RE: SPARE QUOTATION		

Below is the quotation for your RFQ: Email on 20/09/2023 Unit Price **Total Price** No Part Number Description U.M Qty **Delivery Status** 8G2920A01251 SPECIAL BLOCK 1 184.54 184.54 1 ΕA 90 2 3G6310V00152 INPUT SHAFT ΕA 2 28,131.46 56,262.92 90 (NEW UNIT) 3G6310V00152 INPUT SHAFT 2 (17, 820.00)(35,640.00) FA 2a (CORE UNIT SN 0841 & SN 0828) 3 3G6320V04252 PUMP, LUBRICATION EΑ 2 27,382.97 54,765.94 90 (NEW UNIT) PUMP, LUBRICATION 3G6320V04252 EΑ 2 (8,068.50) (16,137.00) 3a (CORE UNIT SN 0809 & SN 0810) Grand Total 59,436.40

Note:

1) Offer validity
2) Terms of payment

: 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes : To be made in full before delivery.

: Subject to prior sale

: There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery

5) Condition

6) Confirmation

3) Cancellation

: Confirmation of availability of goods will be given within 5 working days upon receipt of the

official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

: NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate

Warranty period shall be as follows:

1) New condition

2) Repair condition

: 12 months against manufacturer faults except for consumable items.

: 6 months or 500 hrs against manufacturer faults

for KES DN BHD