

Onezack MRO & Technical Supports (\$A0514868-P) No. 12 Jalan Sorta W; US/W Sek US, Bandar Pinggiran Subang 46150 SHAH ALAM Selangar Darul Ehsen, Malaysia. Tel: +603 78325963 Fax: +603.78325963

Email amranmallog@gmuil.com

## QUOTATION

To: Galaxy Aerospace (M) Sdn. Bhd.

Suite 11-14,

Helicopter Center,

Malaysia Malaysia International Aerospace Centre

Sultan Abdul Aziz Shah Airport

47200 Subang

Selangor Darul Ehsan

Attn: Ms Nor Izzati Azmi

Quote Ref: OMTS/GA/MRO/QT/27(R1)/23

Date: 19th Oct 2023

Your Ref No.: Your Email

Date: 11th Jul 2023

PO Ref No.: PO-GAM-MMA-23-731

Date: 31<sup>st</sup> Jul 2023

## Re: QUOTATION FOR THE SERVICING OF GENTAX HELMET

We are pleased to submit our servicing quotation and lead delivery time as below for your consideration:

ITEM	PART NO.	DESCRIPTION	QTY (EA)	U/PRICE (RM)	AMOUNT (RM)	REMARKS
	FOR THE SE	OR THE SERVICING OF:				
1.	SPH 5	GENTAX HELMET			ì	
	90D7982-2	6 Monthly Servicing (2.5 hrs)	12	255.00	3,060.00	
		S/No.: 1. MMEA/SUS/H-GTX/010 2. MMEA/SUS/H-GTX/014 3. MMEA/SUS/H-GTX/019 4. MMEA/SUS/H-GTX/023 5. MMEA/SUS/H-GTX/027 6. MMEA/SUS/H-GTX/028 7. MMEA/SUS/H-GTX/052 8. MMEA/SUS/H-GTX/056 9. MMEA/SUS/H-GTX/061 10. MMEA/SUS/H-GTX/068 11. MMEA/SUS/H-GTX/074 12. MMEA/SUS/H-GTX/077 W/ Scope: a. Acceptance & Physical Inspection		o B		
		<ul><li>b. Operational &amp; Functional Test</li><li>c. Part Replacement &amp; Cleaning</li><li>d. Functional Test &amp; Repacking</li></ul>				
2		Mandatory Part Replacement				
	2150004	Ear White Cover	12	28.00	336.00	Qty: 12 pairs
3.		Other Part Replacement:	1			
	18434G-02	Mic Protector - (S/No.:H-GTX/010 & H-GTX/014)	2	48.00	96.00	
	9742782	Chin Strap Padding (S/No.: H-GTX/010)	1	150.00	150.00	
	90D7933	Outer Visor (Dark) - (S/No.:H-GTX/014 & H-GTX/019)	2	780.00	1,560.00	
	1	Cable Coil Cord 36 Assembly (H-GTX/014)	1	1,350.00	1,350.00	
4	87B7492-2	Mic Communication Cord (S/No.: H-GTX/019)	1	450.00	450.00	
	09168P-31	Microphone (S/No: H-GTX/061)	1	450.00	450.00	
					7,452.00	
		Sales Service Tax	0%		0.00	
_	The state of the s	TOTAL		1	7,452.00	

## **REMARKS:**

- 1. Certificate Completion of Work (CCOW) will be issued upon completion of work
- 2. Price and delivery quoted are Ex-work Onezack MRO & Technical Supports
- Validity is 30 Days
- 4. Terms: 30 Days
- 5. Price quoted are in Ringgit Malaysia

We trust our quotation will receive your favourable consideration.

for ONEZACK MRO & TECHNICAL SUPPORTS





## **DISCREPANCY REPORT**

OMTSP-A-05B

REFERENCE NO.: OMTSP-A-05B Control No.: OMTS/GA/DR/EW/08/2023						
1. Item: GENTEX HELMET	2. Part No: SPH-5/ 90D7982-2					
3 Serial No: As Listed Below	4. Customer: GALAXY AEROSPACE (M)					
<ol> <li>Customer Indent Order: PO/GAM/MMA/23/731 dtd 31 Jul 23</li> </ol>	<ol><li>Work Required: 6 monthly servicing Work Order No.: OMTS/EW/055/23</li></ol>					
S/No: 1. MMEA/SUS/H-GTX/010 2. MMEA/SUS/H-GTX/014 3. MMEA/SUS/H-GTX/019 4. MMEA/SUS/H-GTX/023 5. MMEA/SUS/H-GTX/027 6. MMEA/SUS/H-GTX/028 7. MMEA/SUS/H-GTX/052 8. MMEA/SUS/H-GTX/056 9. MMEA/SUS/H-GTX/061 10. MMEA/SUS/H-GTX/068 11. MMEA/SUS/H-GTX/074 12. MMEA/SUS/H-GTX/077						
7. Observation:						
a. Physical & Visual Inspection found that Ear white cover (Pt. No.: 2150004) of all the Qty 12 Gentex Helmets listed above have wear & tear.						
b. TDI revealed that the condition of all Helmets is serviceable except for Helmet S/No.:						
i. H-GTX-/010 & /014 with damaged Mic Protector (Pt.No.: 18434G-02) ii. H-GTX/010 with missing Chin Strap Padding (Pt.No.: 9742782) iii. H-GTX-/014 /019 with cracked Outer Visor (Dark) (Pt.No.: 90D7933) iv. H-GTX/014 with defective Cable Coil Cord 36 Assy. (Pt.No.: 87B7491-2) v. H-GTX/019 with defective Microphone Communication Cord (Pt.No.: 87B7492-2) vi. H-GTX-/061 with defective Microphone (Pt.No.: 09168P-31)						
<ul> <li>c. Functional Test on all the above Gentex Helmets found to be serviceable except for Helmet S/No.: H-GTX/014, /019 &amp; 061 where the Communication System (Cable Coil Cord 36 Assy., Mic Comms Cord &amp; Microphone) are defective.</li> <li>8. Finding &amp; Action:</li> </ul>						
a. All missing and defective items stated by Para b (Items i to vi) have been replaced and functional test found all Helmets are serviceable.  QAP / Workshop Supervisor:  Date: 19 Oct 2023						
9. Probably Cause: Missing, Wear & Tear an						
10 Recommended Action Required: Replaced all missing and defective items.  11. Customer Notified reference: N/A  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.  (To be completed by Respective Replaced all missing and defective items.)						
12. Action by Customer: Pace 19 Oct 2023						
Customer Representative: Eng. Dept MMEA Date: 26 10 2022						
14. Action by QA Department:						
QA Manager:	Date:					