


	AVP-AERO VOO DE PORTUGAL Avionics MRO Repair Facility / EASA Repair Station PT.145.039 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal Tel: +351 219 411 208 Fax: +351 219 411 210 www.avp.com.pt email: avp@avp.com.pt <small>VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082</small>			Orçamento Nº Quote Nº 20234330R Page 1-2	
	V. Ref./ Your Ref: GAM/CIPL/23/237	Data/Date	10-05-24		
Para/To:	GALAXY AEROSPACE (M) SDN BHD				
Ao cuidado/ Attn of: IZZATI AZMI	Assunto/ Subject	Repair Quote			
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	418-00468-602	BOX AMPLIFIER TRIM ACTUATOR	6615-14-439-0435	1016	Reparação / Repaired

A. Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Client		
B. Descrição da Avaria feita pela AVP/ Description of Discrepancy found by AVP		B.1- PAGE 2
C. Reparação / Repaired		€ 15 000,00
D. Material substituído/ Material Replaced:		
	Description	
	D.1 Material in page 2	€ -
	Broker and Custom Fees	Included in point C
	Soma / Sum	€ 15 000,00
	Desconto / Discount	€ -
	Valor Final / Final Value	€ 15 000,00
	IVA / Taxes 23%	€ -
	Valor Final Com Iva / Final Value With Taxes	€ 15 000,00
E. Garantia/ Warranty:		O valor monetário usado é Euro Currency quoted in Euro
1 ano sobre a data do certificado / 1 year from date of Certificate		
Garantia é sobre o trabalho realizado e componentes substituídos / Warranty covers work done and parts replaced		
F. Entrega/ Delivery:		
Fob AVP		
10 Dias após aprovação /Days after approval		
G. Observações/ Observations:		
Pagamento/ Payment Proforma Invoice		
Orçamento válido em dias/ Quote Valid in days - 90 days		
Acompanha a unidade Certificado de Conformidade Iso 9001 e Relatório de Reparação The unit is sent with Iso 9001 Certificate of Conformance and Component Condition Report.		

Assinatura:
Signature

Aprova do por
Approved and proceed by: € 15 000,00

Entregar Como Está/
Return As Is € 4 600,00

	AVP-AERO VOO DE PORTUGAL Avionics MRO Repair Facility / EASA Repair Station PT.145.039 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal Tel: +351 219 411 208 Fax: +351 219 411 210 www.avp.com.pt email: avp@avp.com.pt <small>VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082</small>		Orçamento Nº Quote Nº 20234330R Page 2-2		
	V. Ref./ Your Ref: GAM/CIPL/23/237	Data/Date:	10-05-24		
Para/To:	GALAXY AEROSPACE (M) SDN BHD				
Ao cuidado/ Attn of: IZZATI AZMI	Assunto/ Subject	Repair Quote			
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	418-00468-602	BOX AMPLIFIER TRIM ACTUATOR	6615-14-439-0435	1016	Reparação / Repaired

A.1 Avaria Reportada pelo Cliente / Description of Discrepancy Reported by Customer

Nº Relatório Deficiência Cliente/Defect Customer Report UNSERVICEABLE PINK LABEL GALAXY AEROSPACE.
 AIRSPEED NOT FOLLOW BARAN 1+2.

B.1 Avaria detectada pela AVP/ Description of defects found by AVP

The Test Step 4.C.(3).(C) has been failed
 The integrated Circuit M5 on PL108 Yaw trim Circuit must be replaced
 The integrated Circuit M2 on PL109 Elctronic Trim and Transparency Circuit must be replaced

C.1 Teste de inspeção e de bancada/ Bench test of unit

Unidade necessita de ser aberta / Unit requires to be open
 Desmontada / Disassembled
 Localizar avaria / Malfunction found
 Limpeza / Clean
 Substituir componentes / Parts replaced
 Reparação / Repaired
 Ajustes / Adjustements
 Lubrificação / Lubricated
 Montagem / Assembled
 Teste Funcional / Functional Test
 Valores registados / Values Registered
 Valores registados / Values Registered
 Inspeção Final para regressar ao trabalho / Final Inspection to go back to work.

D.1 Material – Details

Part Number	Description	Qty	TAT	Unit Price	Total Price
CD40106BE	Hex Schmitt Trigger Inverter	1	1	0	0
LM124J	Quadruple Operational Amplifier	1	1	0	0
Material with € 0.00 is already included in the repair/Overhaul price				Total	€ -