

## PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE

www.precisionaviationgroup.com GST: 201737172D

## **QUOTATION**

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHAR KHAN SUITE 11-14, HELICOPTER CENTRE, MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

**SUBANG 47200** 

MALAYSIA Tel.: +603-7455 0555

In response to your request, we are pleased to quote you the following:

No. 5606193

Pg:1/2

: Q5606193 Our Ref

:PREPAID WIRE TRANSFR :Ratan Pandey Terms Our Contact

eMail

: rpandey@heliparts.com : May-18-2023 : FCA - FREE CARRIER (ORIGIN) Valid Until Incoterms

: Apr-18-2023 **Quote Date** 

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount			
1	9599-607-18503 TRANSCEIVER, ERT 160 ALT#:ERT-160	RP	1 EA	7 Days	\$ 32,950.00 EA	\$ 32,950.00			
	Note: OUTRIGHT PRICE Schedule B: 8525.60.1050 ECCN: 9A991	DD	4.54	7 Davis	\$ 07 F00 00 FA	<b>6</b> 27 500 00			
2	TRANSCEIVER, ERT 160 ALT#: ERT-160	RP	1 EA	7 Days	\$ 27,500.00 EA	\$ 27,500.00			
	Note: ** Exchange Charge- Core Return Require Schedule B: 8525.60.1050 ECCN: 9A991		454	O4I-					
3	TRANSCEIVER, ERT 160 ALT#: ERT-160	AR	1 EA	Stock					
	Note: ** Core Charge ** Schedule B: 8525.60.1050 ECCN: 9A991								
	Certification Type: FAA 8130								
	Exchange Policy								
	Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion, cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days								

1. ALL QUOTES ARE SUBJECT TO CHANGE WITHOUT NOTICE

2. ALL ITEMS ARE SUBJECT TO PRIOR SALE

3. ALL EXCHANGE CORES ARE DUE WITHIN 30 DAYS AND MUST BE THE SAME MANUFACTURERS PART NUMBER AS UNIT SOLD.

4.PAG RESERVES THE RIGHT TO BILL BACK ANY OVERAGES FOUND WITH RETURNED CORES

Continued on next page...

Copyright (c)PENTAGON2000 Software, Inc.

ORIGINAL (COPY.)



## PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

## **QUOTATION**

Our Ref : Q5606193 Quotation No. 5606193 Page :2/2

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount					
	of date of invoice, the applicable core charge will	be d	ue.								
	All units quoted are subject to prior sale										
	Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer.										
			Sub Total:	\$ 60,450.00							
1. ALL QI	JOTES ARE SUBJECT TO CHANGE WITHOUT NOTICE EMS ARE SUBJECT TO PRIOR SALE										
3. ALL EX	(CHANGE CORES ARE DUE WITHIN 30 DAYS AND MUST										
	AME MANUFACTURERS PART NUMBER AS UNIT SOLD. ESERVES THE RIGHT TO BILL BACK ANY OVERAGES FO										
					Total: [USD]	\$ 60,450.00					
Ratan Pa	andey,				Totali [OOD]	Ψ 00, +30.00					

Copyright (c)PENTAGON2000 Software, Inc. Ser #:[2000.21267] Ver 2019.01.01 Build 14

ORIGINAL (COPY.)