

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

EXCHANGE QUOTE

3:25 AM



Print No. : Pg:1/2

Printed By: RIDZUAN BIN YA'AKOB

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHÀR KHAN

SUITE 11-14, HELICOPTER CENTRE, MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Print Date: May-12-2023

Tel.: +603-7455 0555

In response to your request, we are pleased to quote you the following:

No. 5606362

:Q5606362 Our Ref

Terms :PREPAID WIRE TRANSFR

Our Contact : Ratan Pandey

eMail : rpandey@heliparts.com : Jun-11-2023 Valid Until

: FCA - FREE CARRIER (ORIGIN) Incoterms

Quote Date : May-12-2023

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	066-03137-3200 ELECTRONIC DISPLAY ALT#: ED-551A MFG: (BKR) BENDIX/KING CORPORATION	ОН	1 EA	4 Days	\$ 14,950.00 EA	\$ 14,950.00
2	Note: ** Exchange Charge- Core Return Required 066-03137-3200 ELECTRONIC DISPLAY ALT#: ED-551A MFG: (BKR) BENDIX/KING CORPORATION	AR	1 EA	Stock		
3	Note: ** Core Charge [\$ 5,000.00]** 066-03137-3200 ELECTRONIC DISPLAY ALT#: ED-551A MFG: (BKR) BENDIX/KING CORPORATION Note: OUTRIGHT PRICE	ОН	1 EA	4 Days	\$ 19,500.00 EA	\$ 19,500.00
	Certification Type: FAA8130					
	Exchange Policy					
	Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion, cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days of date of invoice, the applicable core charge will be due.					

Continued on next page...



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

797523
SINGAPORE
www.precisionaviationgroup.com
GST: 201737172D

Total:

[USD]

EXCHANGE QUOTE

Printed By: RIDZUAN BIN YA'AKOB Print Date: May-12-2023 3:25 AM Print No. Our Ref Q5606362 Quotation No. 5606362 Page:2/2 Line P/N & Description Cn Qty Bid Delivery Unit Price **Amount** All units quoted are subject to prior sale Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer. Sub Total: \$ 34,450.00

\$ 34,450.00

RIDZUAN BIN YA'AKOB,