



406 Dividend Drive
 Peachtree City, Georgia 30269
 Phone (770) 632-1851
 Fax: (770) 632-1852

Repair Estimate

LOG CARD:	YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
SPECIAL INSTRUCTION:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
UNIT MISUSED:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PICTURES:	<input type="checkbox"/>	<input checked="" type="checkbox"/>

DATE:	18-Jan-2022
PRIME REFERENCE:	50238
CUSTOMER REFERENCE:	PO-21-4321
PART NUMBER:	524-062
SERIAL NUMBER:	1080
DESCRIPTION:	STARTER GENERATOR
WORK REQUESTED:	TEST

EVALUATIONS / FINDINGS:

**** DUE TO DAMAGE, THIS QUOTE IS PRELIMINARY ****

DEB RECEIVED DAMAGED, DE BEARING IS DAMAGED, (4) DE SCREWS STRIPPED- REPLACMENT OF ALL REQUIRED
 UNIT RESISTANCE AT 2M+ OHMS, SHUNT AT 1.9 OHMS, BRUSHES APPEAR TO BE AT 100%. COMMUTATOR HAS DARK EVEN
 FILM WITH SMOOTH APPEARANCE.

UNIT REQUIRES REPAIR BEFORE A FULL TEST CAN BE PERFORMED.

CORRECTIVE ACTIONS TO BE CARRIED OUT:

UNIT REQUIRES REPAIR BEFORE A FULL TEST CAN BE PERFORMED.

PARTS REPLACED OR REPAIRED

EXCLUSIONS:	<input type="text"/>	CONDITION AFTER COMPLETION:	<input type="text" value="REPAIRED"/>
--------------------	----------------------	------------------------------------	---------------------------------------

PART NUMBER	DESCRIPTION	STATUS	QUANTITY	PRICE

FLAT RATE:	<input type="text"/>	COMMENTS: PARTS (ENDBELL AND BEARING)- \$4560.00 LABOR- \$850.00 TAT DEPENDANT ON PARTS AVAILABILITY
TOTAL QUOTE	<input type="text" value="\$5,400.00"/>	
TOTAL QUOTE OPTION #1	<input type="text"/>	
TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)	<input type="text" value="60"/>	

Approval Signature: _____

Name: _____ Date: _____