



B R E E Z E • E A S T E R N

Be Ready. Be Sure.

Sales Quotation

R901015

Customer No. 3393	Customer RFQ No. AERO/2021/018	Coordinator Jabbie, Sahid	Quotation Date 8/10/2021
Terms of Delivery FOB - Whippany	Reference R4015989	Customer PO AERO/2021/018	Expiration Date 11/8/2021
		End User	Revision No. 1

Customer Address

CHOPPERTECH SERVICES SDN BHD
38 & 38-1, JALAN TPS 1/7
TMN PELANGI SEMENYIH
43500 SEMENYIH SELANGOR
MALAYSIA

Delivery Address

CHOPPERTECH SERVICES SDN BHD
38 & 38-1, JALAN TPS 1/7
TMN PELANGI SEMENYIH
43500 SEMENYIH SELANGOR
MALAYSIA

Breeze-Eastern thanks you for the opportunity to submit the following per your request. When issuing a Purchase Order for this/these Part Number(s) please reference our Quote Number R901015

Line	Part No.	Part Description	Quantity	U/M	Ready ARO (days)
		<i>Export Cat No.</i>			
1	CH-9020-1-R	(C) CARGO HOOK SUPPORT SN TR0385			90
	C-CH FAA-PMA		1	EA	
		9A991.d \9801.10.0000			

(-R) after Breeze part number is strictly for internal administrative purposes only. This is not part of the Breeze part number.

THE ABOVE UNIT WAS RETURNED FOR OVERHAUL.

Summary of Findings - The Support Frame SN TR0385 was returned for overhaul. The frames was manufactured December 2015. The frame was received with hook SN B4383. The frame was evaluated. Frame SN TR0385 will be replaced with a new frame SN will be advised. The new frame will be tested and certified to the latest revision.

Please submit your purchase order to reflect the Service Cost and Estimated Date of Shipment as the date of purchase order amendment plus 90 days. Per Breeze-Eastern policy, the purchase order will NOT be accepted if the Service Cost or Estimated Date of Shipment is stated incorrectly. This quote is valid for 90 days, after 90 days the service will be subject to requote for increased material costs and storage fees. The evaluation fee is \$4,851.00 and is waived with an amended Purchase Order with the accurate Service Cost. If after receiving the quotation the decision is made to not fund the repair, a purchase order for the evaluation fee is required and the unit will be returned in a disassembled condition.

The quoted price does not include any freight/shipping charges. Please provide the preferred return shipping method Name of Carrier, Service, and Account Number.

The quoted service cost represents the typical parts replacement and the associated labor content after an initial evaluation. The Ready ARO (days) is the estimated service time on a best effort basis and starts after receipt of amended Purchase Order and authorization to proceed. Based on outside processing of major components, replacement material beyond the scope of the initial evaluation may be required subsequently affecting the service cost and estimated service time. In this instance, Breeze-Eastern reserves the right to extend an over and above quotation to cover the additional service cost.

All mandatory ECOs will be incorporated. The unit is to be tested and certified to the latest revision with issuance of FAA/EASA. All parts removed from the unit during the service process and not reused in the rebuild process will be scrapped when the unit is



B R E E Z E • E A S T E R N

Be Ready. Be Sure.