



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

EXCHANGE QUOTE



Print Date : Jan-24-2023 8:53 PM

Printed By : RIDZUAN BIN YA'AKOB Print No. : 1

For : Account No. [GALAXYMY]

No. 5605709

Pg:1/1

GALAXY AEROSPACE (M) SDN BHD
 Attn: NUR AFRINA AZHAR KHAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +603-7455 0555

Our Ref : Q5605709
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : Feb-23-2023
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : Jan-24-2023

In response to your request, we are pleased to quote you the following:

| Line | P/N & Description | Cn | Qty Bid | Delivery | Unit Price | Amount |
|------|---|----|---------|----------|--------------|-------------|
| 1 | 90-380001-23 MASTER CYLINDER ALT#: CM1000-23 MFG: (RAPID*) BEEHCRAFT - WICHITA Note: ** Exchange Charge- Core Return Required ** | SV | 2 EA | 5 Days | \$ 595.00 EA | \$ 1,190.00 |
| 2 | 90-380001-23 MASTER CYLINDER ALT#: CM1000-23 MFG: (RAPID*) BEEHCRAFT - WICHITA Note: ** Core Charge [\$ 350.00]** Certification Type: FAA8130 Exchange Policy Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion, cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days of date of invoice, the applicable core charge will be due. All units quoted are subject to prior sale Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer. | AR | 2 EA | Stock | | |

Sub Total: \$ 1,190.00

Total: [USD] \$ 1,190.00

RIDZUAN BIN YA'AKOB,