

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

797523 SINGAPORE www.precisionaviationgroup.com GST: 201737172D

REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHAR KHAN SUITE 11-14, HELICOPTER CENTRE,

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Tel.: +603-7455 0555

No. 5606730

Pg:1/1

Our Ref : SO# 5604187 Your Ref

: MMA-23-684 : PREPAID WIRE TRANSFR Terms

Our Contact : Ratan Pandey eMail

Valid Until

: rpandey@heliparts.com : Aug-12-2023 : FCA - FREE CARRIER (ORIGIN) Incoterms

: Jul-13-2023 **Quote Date**

	4.000 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00					
Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	524-031 STARTER GENERATOR ALT#: 704A46101011 Serial No(s).: 5174 ECCN: 9A991 Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND Preliminary Inspection: Unit received in bad condition Unit failed incoming tests T-block cover missing, requires replacement US Screen detached from fan cover, rerequires repla Armature found corroded, requires rework USD Stator failed Hi-pot testing, requires rework USD Unit requires replacement of parts and standard Standard overhaul USD 4,250.00 Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, NOTE- This unit is on hold pending your faxed/a any applicable taxes, freight or customs charged during the course of the repairs listed above. If	OH ADVISE ADVISE ADVISE 1,750.00 1,750.00 overhaul TESTED emailed as s. This est	JSD1,895.00 AND RECERTIFIED. uthorization to proceed. imate does not include a	This estimate dany add'l failure	\$ 10,140.00 EA	\$ 10,140.00
	Approval Signature:		Date:		Sub Total:	\$ 10,140.00
RIDZUA	N BIN YA'AKOB.				Total: [USD]	\$ 10,140.00