

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

797523 SINGAPORE www.precisionaviationgroup.com GST: 201737172D

REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD

Attn: MUZDALIFAH

SUITE 11-14, HELICOPTER CENTRE,

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Tel.: +60377347226

No. 5608281

Pg:1/2

Our Ref

: SO# 5604732 : PO-23-7499 Your Ref

: PREPAID WIRE TRANSFR Terms **Our Contact** : Ratan Pandey

eMail

Valid Until

: rpandey@heliparts.com : May-21-2024 : FCA - FREE CARRIER (ORIGIN) : Apr-21-2024 Incoterms

Quote Date

-609 ROL PANEL ASSEMBLY 3G2591V02351 No(s).: 00061 : 9A991.d ted By Customer: INOP. Inspect and Advise inary Inspection: ceived in fair condition iled incoming test and GND reading is out of range ontrol switch found damaged, requires replace	RP	1 EA	60 Days	\$ 32,515.00 EA	\$ 32,515.00
inary Inspection: ceived in fair condition iled incoming test nd GND reading is out of range					
iometer meter found defective, requires replace iometer meter found defective, requires replaced quires replacement of parts and standard repard repair USD 27,500.00 USD 32,515.00	cemen	- USD 5,015.00 t			
tive Action: to be Repaired per CMM and tested and rece	ertified.				
plicable taxes, freight or customs charges. The	his estir	mate does not include ar	ny add'l failures t	that may be found	
/al Signature:		Date:			
		- This unit is on hold pending your faxed/emailed au oplicable taxes, freight or customs charges. This esting the course of the repairs listed above. If add'l repair	This unit is on hold pending your faxed/emailed authorization to proceed. Toplicable taxes, freight or customs charges. This estimate does not include a the course of the repairs listed above. If add' repairs are needed, we will co	- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate doe oplicable taxes, freight or customs charges. This estimate does not include any add'l failures the course of the repairs listed above. If add'l repairs are needed, we will contact you with a	- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include oplicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate.

Continued on next page...



Our Ref

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

797523 SINGAPORE www.precisionaviationgroup.com GST: 201737172D

REPAIR / OVERHAUL QUOTE

SO# 5604732 PO-23-7499 Quotation No. 5608281 Page: 2/2 Your Ref Line P/N & Description Cnd Qty Bid Delivery Unit Price **Amount** \$ 32,515.00 Sub Total: Total: [USD] \$ 32,515.00

Copyright (c) PENTAGON 2000 Software, Inc. Ser #:[2000.21267] Ver 2019.01.01 Build 14

RIDZUAN BIN YA'AKOB,

ORIGINAL (COPY.)