



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

No. 5608331 Pg:1/1

GALAXY AEROSPACE (M) SDN BHD
 Attn: MUZDALIFAH
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +60377347226

Our Ref : SO# 5604735
Your Ref : PO-23-7505
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : Jun-05-2024
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : May-06-2024

| Line | P/N & Description | Cnd | Qty Bid | Delivery | Unit Price | Amount |
|------|--|-----|---------|----------|----------------|-------------|
| 1 | 822-1377-001 GLOBAL POSITIONING SENSOR ALT#: GPS-4000A Serial No(s): 10NJK ECCN: 7A994 Reported By Customer: GPS FAILED TO CAPTURE PRESENT POSITION Preliminary Inspection: UNIT RECEIVED IN FAIR CONDITION UNIT FAILED BENCH TEST UNIT REQUIRES NEW LABEL CAPACITOR FOUND FAULTY, REQUIRES REPLACEMENT TO RESTORE NORMAL OPERATION ON ATE AND TO UNDERGO FINAL TEST UNIT REQUIRES STANDARD REPAIR - USD 5,950.00 Corrective Action: UNIT WILL BE REPAIRED AS PER CMM AND TESTED TO PASS ALL FUNCTIONS. NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate. Approval Signature: _____ Date: _____ | RP | 1 EA | 30 Days | \$ 5,950.00 EA | \$ 5,950.00 |

| | |
|---------------------|-------------|
| Sub Total: | \$ 5,950.00 |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Total: [USD] | \$ 5,950.00 |

RIDZUAN BIN YA'AKOB,