

#### PRIME INDUSTRIES, INC.

406 Dividend Drive Peachtree City, GA 30269 Tel: (770) 632-1851

UNITED STATES Fax: (770) 632-1852 www.primeindustriesusa.com



### REPAIR & OVERHAUL QUOTE

Print Date : Mar-13-2024 1:59 PM		Printed By : Ma	rc Lacourly Print No. : 1
For : Account No. [GALAXY REP]	No. 123	3382	Pg:1/3
GALAXY AEROSPACE (M) SDN BHD Attn: MUZDALIFAH ROSLIZAN SUITE 11-14 HELICOPTER CENTRE MALAYSIA INTL AEROSPACE CENTRE SULTAN ABDUL AZIZ SHAH AIRPORT SUBANG SELANGOR 47200 MALAYSIA Tel. : 603 77347226 Fax : 603 60377347526 In response to your request, we are pleased to quote you the following:	Our Ref Your Ref. Fin.Dest. Terms Our Contact eMail Valid Until F.O.B. Quote Date Our S.O. Cust P.O.	: 123382-ML : PO-24-7744 : MALAYSIA : NET-30 DAYS : KIMBERLY CHANCE : <u>KIMBERLY@PRIMEII</u> : Apr-12-2024 : EX-WORKS : Mar-13-2024 : 046434 : PO-24-7744	NDUSTRIESUSA.COM

P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
THE EXT/RET MOTOR PULLS EXCESS AMPS; THE EXT/RET MOTOR PULLS EXCESS AMPS; THE UNIT IS DIRTY AND CONTAMIN	HE RC	TATION MOTOR IS INT			
<ol> <li>Prime Industries' Standard Terms &amp; Conditions of Sale apply, see WWW.PRIMEINDUSTRIESUSA.COM.</li> <li>Prices &amp; deliveries are quoted in business day and are applicable to the quantities as covered by this quotation.</li> <li>All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.</li> <li>In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.</li> <li>If an Export License is required, a \$250.00 processing fee will apply for each occurrence</li> <li>Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package. FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed</li> </ol>				Continued on	next page
	930-500-25-1 SEARCH LIGHT I/W: 90-060-1 Serial No.: 071302 MFG: (LUMINATOR) LUMINATOR AEROSPACE Note: OVERHAUL QUOTE PRIME PO NUMBER: 056831 UNIT MISUSED: NO EVALUATIONS/FINDINGS: THE EXT/RET AND RO THE EXT/RET MOTOR PULLS EXCESS AMPS; TI REPLACED; THE UNIT IS DIRTY AND CONTAMIN CONDITION AFTER COMPLETION: OVERHAULE EXCLUSIONS: 932-130-00 MOTOR, EXT/RET (1): \$2,365.00 932-230-00 MOTOR, ROTATION (1): \$2,596.00 4580 LAMP (1): \$75.00	930-500-25-1       OH         SEARCH LIGHT       I/W: 90-060-1         Serial No(s):: 071302       Serial No.: 071302         MFG: (LUMINATOR) LUMINATOR AEROSPACE       Note: OVERHAUL QUOTE         PRIME PO NUMBER: 056831       UNIT MISUSED: NO         EVALUATIONS/FINDINGS: THE EXT/RET AND ROTATINTHE EXT/RET MOTOR PULLS EXCESS AMPS; THE ROREPLACED; THE UNIT IS DIRTY AND CONTAMINATED         CONDITION AFTER COMPLETION: OVERHAULED         EXCLUSIONS:         932-130-00 MOTOR, EXT/RET (1): \$2,365.00         932-230-00 MOTOR, ROTATION (1): \$2,596.00         4580 LAMP (1): \$75.00	930-500-25-1       OH       1 EA         SEARCH LIGHT       I/W: 90-060-1       0H       1 EA         Serial No(s):: 071302       Serial No:: 071302       0H       1 EA         Serial No:: 071302       Serial No:: 071302       0H       1 EA         Write: OVERHAUL QUOTE       PRIME PO NUMBER: 056831       0H       0H       1 EA         UNIT MISUSED: NO       EVALUATIONS/FINDINGS: THE EXT/RET AND ROTATION MOTORS ARE BAD;       1HE ROTATION MOTORS ARE BAD;         THE EXT/RET MOTOR PULLS EXCESS AMPS; THE ROTATION MOTORS ARE BAD;       1HE ROTATION MOTOR IS INT         REPLACED; THE UNIT IS DIRTY AND CONTAMINATED.       CONDITION AFTER COMPLETION: OVERHAULED         EXCLUSIONS:       932-130-00 MOTOR, EXT/RET (1): \$2,365.00       932-230-00 MOTOR, ROTATION (1): \$2,596.00         4580 LAMP (1): \$75.00       Industries' Standard Terms & Conditions of Sale apply, see WWW.PRIMEINDUSTRIESUSA.COM.       & deliveries are quoted in business day and are applicable to the quantities as covered by this quotation.         erials quoted from stock or with deliveries of 15 days or less are subject to prior sale.       Event of an order, the above commodities are not to be shipped to any country that has an embargo againstit by the U.S. Government. Should these commodities require an export license, it shall be sponsibility to comply with the United States Department of State/Commerce Export Regulations.         sport License is required, a \$250.00 procexisting fee will apply for each occurrence to us Mate	930-500-25-1       OH       1 EA       60 Days         SEARCH LIGHT       I/W: 90-060-1       5erial No.; 071302       5erial No.; 071302         Serial No.; 071302       Serial No.; 071302       Serial No.; 071302         Serial No.; 071302       Serial No.; 071302       60 Days         MFG: (LUMINATOR) LUMINATOR AEROSPACE       Note: OVERHAUL QUOTE       PRIME PO NUMBER: 056831         UNIT MISUSED: NO       EVALUATIONS/FINDINGS: THE EXT/RET AND ROTATION MOTORS ARE BAD; OPENED NUIT         THE EXT/RET MOTOR PULLS EXCESS AMPS; THE ROTATION MOTOR IS INTERMITTENT; TI         REPLACED; THE UNIT IS DIRTY AND CONTAMINATED.         CONDITION AFTER COMPLETION: OVERHAULED         EXCLUSIONS:         932-230-00 MOTOR, ROTATION (1): \$2,596.00         4580 LAMP (1): \$75.00         Industries' Standard Terms & Conditions of Sale apply, see WWW.PRIMEINDUSTRIESUSA.COM.         & deliveries are quoted in business day and are applicable to the quantities as covered by this quotation.         eraids quoted from stock or with deliveries of 15 days or less are subject to prior sale.         event of an order, the above commodities are not to be shipped to any county that has an embargo against it by the U.S. Government. Should these commodities require an export license, it shall be sponsibility to comply with the United States Department of State/Commerce Export Regulations.         xport License is required, a \$250.00 processing fee will apply for each occurrence to us Mate	930-500-25-1 SEARCH LIGHT IW: 90-060-1 Serial No(s): 071302       OH       1 EA       60 Days       \$ 7,336.00000 EA         Serial No: 071302       Serial No: 071302       Serial No: 071302       \$ 7,336.00000 EA         MEG: (LUMINATOR) LUMINATOR AEROSPACE Note: OVERHAUL QUOTE       PRIME PO NUMBER: 056831       Image: 100 minipulation of the second of



### PRIME INDUSTRIES, INC.

406 Dividend Drive Peachtree City, GA 30269 Tel: (770) 632-1851

UNITED STATES Fax: (770) 632-1852 www.primeindustriesusa.com



# REPAIR & OVERHAUL QUOTE

-	: Mar-13-2024 1:59 PM	in Doct				CLacourly Print No. : 1
Our Ref Your Ref.		in.Dest.	: MALAYSIA		Quotation No. 12	23382 Page:2/3
Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
	FLAT RATE: \$2,300.00					
	TOTAL QUOTE: \$7,336.00					
	EVALUATION FEE IF QUOTE DENIED: \$					
	TURN AROUND TIME (DAYS): 60 DAYS					
	APPROVAL SIGNATURE:	DA	TE:			
	NAME:					
	*** END-USE INFORMATION ***					
	EXPORTING TO : MALAYSIA					
	APPLICATION :STOCK					
	SCHEDULE B / H.S. # :8807.30.0060					
	ECCN: 9A991					
	ESTIMATE QUOTES DEPENDING ON CONDI		THE UNITS.			
	EXPORT COMPLIANCE STATEMENT					
	Products sold by PRIME INDUSTRIES, INC. ma		a licansa from tha LLS [	Anartmont of St	ato	
	the U.S. Department of Commerce, or the U.S. I	· .		1.		
	out of the United States. PRIME INDUSTRIES,	•			rahle	
	United States Export Control Regulations includ		·			
	United States Export control regulations includ					
1 Drimo li	adustrias' Standard Tarms & Canditians of Sala apply, see W					
2. Prices &	<ol> <li>Prime Industries' Standard Terms &amp; Conditions of Sale apply, see WWW.PRIMEINDUSTRIESUSA.COM.</li> <li>Prices &amp; deliveries are quoted in business day and are applicable to the quantities as covered by this quotation.</li> <li>All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.</li> <li>In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be</li> </ol>					
placed a						
your responsibility to comply with the United States Department of State/Commerce Export Regulations. 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.			Continued on next page			
FN=Facto	ry New/NS=New Surplus/OH=Overhaul Certified/SV=Service	able/RP=Re	paired/AR=As Removed			



### PRIME INDUSTRIES, INC.

406 Dividend Drive Peachtree City, GA 30269 Tel: (770) 632-1851

UNITED STATES Fax: (770) 632-1852 www.primeindustriesusa.com



# REPAIR & OVERHAUL QUOTE

Print Date	e : Mar-13-2024 1:59 PM				Printed By : Marc	Lacourly Print No. : 1
Our Ref Your Ref.	: 123382-ML : PO-24-7744	Fin.Dest.	: MALAYSIA		Quotation No. 123	3382 Page: 3/3
Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
	in Arms Regulations (ITAR), the Export A	dministration Regul	ations (EAR), Office	of Foreign		
	Assets Control (OFAC), and the Foreign	F F		U U		
	of products requiring a license from the L		· · · ·		2	
	and/or the U.S. Department of Treasury i	·	•			
	correspondence may contain technical d	, , , , , , , , , , , , , , , , , , ,	5			
	Traffic in Arms Regulations (ITAR) and/o		•			
	proper approval from the U.S. Department	•	•		r	
	or release of this technical data to a forei					
	United States or abroad, is strictly prohib					
	United States of abroad, is strictly prohib	neu.				
	THANK YOU FOR YOUR ORDER					
					Sub Total:	\$ 7,336.00
1. Prime Ir	ndustries' Standard Terms & Conditions of Sale appl	y, see WWW.PRIMEIND	USTRIESUSA.COM.			
	& deliveries are quoted in business day and are appl			ı. —		
<ul> <li>All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.</li> <li>In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.</li> </ul>						
your responsibility to comply with the United States Department of State/Commerce Export Regulations. 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence						
	ous Material (HAZMAT) Shipments shall be subject to ry New/NS=New Surplus/OH=Overhaul Certified/SV			package.		
I IN=FdCl0	i y ivewinio=ivew ou plus/On=Overilaul Certilleu/SV	-Seiviceable/Kr=Kepäll				
				1	otal: [USD]	\$ 7,336.00