

**H.K JAYA ENGINEERING - ( Reg. no: 001462051 - V )**

No. 10 Jalan Emas 13,  
Bandar Sungai Emas 42700 Banting, Selangor  
Fax - (603) - 3180 1457, Tel - (603) - 3180 1457  
E - Mail: [admin@hkjaya.com](mailto:admin@hkjaya.com)



Our Ref : **QUO – 160822-01** Your Ref :  
Date : 2022, 16 August

Messrs : Universiti Kuala Lumpur - Malaysian Institute of Aviation Technology  
(UniKL MIAT), Subang Campus (Universiti Kuala Lumpur - Malaysian Institute of Aviation  
Technology (UniKL MIAT), Kampus Subang)

Attn : Maintenance personnel  
Area : Subang Airport

**QUOTATION OF REPAIR GROUND POWER UNIT ( CONVERTER TYPE )**

We thank you for your kind interest and we are pleased to quote you as follows:

No	Description	QTY	Amount (RM)
1	To do troubleshooting of the defective GPU unit and found out power inverter module ( Power VMP code PVRSP-3000-24 ) defective. To dismantle power inverter module and sent out to electronic shop to check and quote for repair	1 Lot	RM 1 560
2	To repair ( Power VMP code PVRSP-3000-24 ) -Repair and service engineering charge -Change the faulty parts -Test the functionality of the unit  Warranty : 3 Months	1 Lot	RM 2 250
3	Transport	1 Lot	Inc
			<b>RM 3 810</b>

Assuring you our best quality and prompt services.  
Looking forward to serve you soon.

Thank You.

for H.K. Jaya Engineering.

(Aizat Hamdan)  
Operation Manager